Lonnie Peterson / TMS Toyota Customer Services Product Quality and Service Support, Quality Compliance August 3, 2010

Approved By: George Morino

To:

All Toyota Dealers


From:

**Toyota Customer Services** 

## 

## Software Update:

We have received a small number of reports indicating the Skid Control ECU may become locked during reprogramming for safety recall A0G. In response to these reports Toyota has developed a new version of software to reduce and prevent the Skid Control ECU from being locked during reprogramming. Please ensure you have the updated software "v222 - 2003 Sequoia VSC Calibration Update" installed prior to performing the A0G reprogramming procedure.



Newly revised technical instructions are available on TIS that explain the software update procedure.

## Note:

Technicians will also be required to adjust the screen saver, and monitor off settings on their Techstreams. Failure to use the new software, or adjust the screen settings will result in permanent ECU damage during reprogramming which will require ECU replacement.