



Subarunet Announcement

To: All Subaru Dealers
From: Subaru of America, Inc.
Date: May 28, 2010

Subject: Subaru Recall WVQ-27 Update
2010 Legacy/Outback CVT Transmission Fluid Cooler Inlet Hose

On May 12, 2010, Subaru of America, Inc. initiated a voluntary Safety Recall to inspect and possibly replace the transmission fluid cooler inlet hose on certain 2010 Legacy and Outback models equipped with a Continuously Variable Transmission (CVT) produced between July 31, 2009 and December 1, 2009. The affected VIN range is as follows:

2010 Legacy A3215537 through A3227670
2010 Outback A3317662 through A3346480

Please be advised of the following updated information concerning this recall:

- **Campaign Bulletin:** The WVQ-27 Campaign Bulletin is now available on the Subaru Technical Information System (STIS) website.
- **Dealer Affected VIN lists:** Affected VIN lists will be mailed to dealers during the week of June 7, 2010.
- **Owner Notification:** Owner notification letters are scheduled to be mailed during the week of June 7, 2010.
- **Repair Parts:** Beginning June 2, 2010, dealers will automatically be sent replacement parts (Hose-CVTF 45520AJ021) equivalent to 20% of their affected VIN count.