

SUBJECT Recall 229: Driver's Airbag Clockspring Connector Shim MY 2010 - 2011 S80, XC70; 2011 XC60; 2010 V70				GROUP 36	NO 229		
COPY TO / CIRCULATIONS (PLEASE INITIAL)				MARKET United States, Canada	PAGE 1 of 1		
GENERAL MGR	PARTS MGR	SERVICE MGR	SALES MGR	DATE	YEAR	MONTH	DAY
					2010	10	20

Reference Bulletins: SMB 36-229
RTJ 22855

Volvo Cars of North America, LLC (Volvo) has decided to conduct a voluntary safety recall on certain model year 2010 - 2011 S80, XC70, 2011 XC60 and 2010 V70 vehicles.

Volvo has identified that there may be an intermittent fault in the driver's airbag clockspring wiring connector for the Supplemental Restraint System (SRS). If this condition occurs, the SRS lamp will be permanently illuminated along with the following message in the Drivers Information Module (DIM) "AIRBAG SYSTEM SERVICE REQUIRED".

If the condition occurs during driving, and if the driver ignores the warning, should an accident occur where the deployment of the driver's airbag is required, the driver's airbag may not deploy as intended or not deploy at all. This poses an unreasonable risk to motor vehicle safety.

The corrective action is to install a metal shim in the driver's airbag clockspring wiring connector.

This recall affects 9,746 vehicles in the U.S and 1,157 in Canada.

The following part numbers apply:

Part Number	Description	Qty
31322719	Shim	1

* A 50% parts allocation of part# 31324709 was distributed to retailers on Monday October 11th.

"Fixed Right — First Time"

