



Hyundai de Puerto Rico
(Sojitz de Puerto Rico Corporation)
101 Ave Conquistadores Cataño PR 00962
Tel: (787) 999-3333 Fax: (787) 999-3355
www.hyundaipr.com

February 2010

37_09V-317.BeltTensionClip_7A173680

MARIA BOYD ABAD
CEIBA B2
MANSIONES DEL SUR CALLE
Coto Laurel PR 00780

RE: IMPORTANT SAFETY RECALL NOTIFICATION
(Seat Belt Tension Sensor Wiring – Recall No. 10V-007)

VIN: KMHFC46F57A173680

Dear 2006-2009 Azera Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Hyundai has decided that a defect, which relates to motor vehicle safety, exists in certain model year 2006 and 2009 Hyundai Azera vehicles produced during the period beginning September 27, 2005 through October 1, 2008.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

What is the problem?

Repeated use of the right front seat belt may cause damage to the seat belt tension sensor wiring. If the seat belt tension sensor wiring becomes damaged, the Air Bag warning lamp in the instrument cluster will illuminate to indicate that a problem exists in the air bag system. If the seat belt tension sensor wiring harness is damaged, the passenger air bag will not deploy if a crash of sufficient force to require front air bag deployment is experienced.

What will Hyundai do?

We are asking you to schedule an appointment to take your vehicle to your Hyundai dealer. For vehicles that experience illumination of the Air Bag warning lamp in the instrument cluster as a result of damage to the seat belt tension sensor wiring, the Hyundai dealer will replace the right front seat belt assembly and install a new seat belt tension sensor wiring harness clip. For vehicles that have not experienced illumination of the Air Bag warning lamp in the instrument cluster as a result of damage to the front seat belt tension sensor wiring, the Hyundai dealer will reroute the right front seat belt tension sensor wiring and secure it with a new harness clip. This procedure will be performed at no charge to you. Repair times will vary and depend on your dealer's appointment schedule.

What should you do?

We urge you to call your Hyundai dealer to schedule an appointment to have this work performed as soon as possible.

What if you have other questions?

If you have any difficulty having this repair performed, we recommend that you call Hyundai de Puerto Rico at 787-999-3333. If you are still not satisfied that we have remedied this situation without charge, and within a reasonable amount of time, you may wish to write to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, D.C. 20590, or call their toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

We urge your prompt attention to this matter.

Hyundai de Puerto Rico.



Hyundai de Puerto Rico
(Sojitz de Puerto Rico Corporation)
101 Ave Conquistadores Cataño PR 00962
Tel: (787) 999-3333 Fax: (787) 999-3355
www.hyundaipr.com

Febrero 2010

37_09V-317.BeltTensionClip_7A173680
MARIA BOYD ABAD
CEIBA B2
MANSIONES DEL SUR CALLE
Coto Laurel, PR 00780

RE: NOTIFICACION IMPORTANTE DE CAMPAÑA DE SEGURIDAD
(Cableado del Sensor de Tensión del Cinturón de Seguridad – Campaña no. 10V-007)

VIN: KMHFC46F57A173680

Estimado Dueño de Hyundai Azera 2006-2009:

Este aviso es enviado a usted de acuerdo a los requisitos del **“National Traffic and Motor Vehicle Safety Act”**.

Leyes federales requieren que cualquier arrendador de vehículos recibiendo este aviso debe remitir una copia de esta notificación al arrendatario dentro de un plazo no mayor de diez días.

Hyundai ha decidido que existe un defecto, relacionado a la seguridad de vehículos de motor en ciertos modelos Hyundai Azera 2006 al 2009 producidos durante el periodo comenzando 27 de septiembre de 2005 hasta 1 de octubre de 2008.

¿Cual es el problema?

El uso repetido del cinturón de seguridad derecho puede causar daños al cableado del sensor de tensión del cinturón de seguridad. Si este cableado sufre daños, la luz de aviso de “Air Bag” puede iluminarse indicando que existe un problema en el sistema de bolsas de aire. Si el cableado del sensor de tensión del cinturón de seguridad sufre daños, la bolsa de aire del pasajero no se desplegara, si un accidente de suficiente magnitud que requiera el despliegue de la bolsa de aire delantera es experimentado.

¿Que hará Hyundai?

Le estamos pidiendo coordine una cita lo antes posible para poder llevar su vehículo a un concesionario Hyundai. Para vehículos que presenten la luz de aviso de “Air Bag” encendida como resultado de daños al cableado del sensor de tensión del cinturón de seguridad, Hyundai reemplazara el cinturón de seguridad delantero derecho e instalara un “clip” para el cableado del sensor de tensión. Para vehículos que no presenten la luz de aviso de “Air Bag” encendida como resultado de daños al cableado del sensor de tensión del cinturón de seguridad, Hyundai redireccionará el cableado del sensor de tensión del cinturón de seguridad delantero derecho y lo asegurara con un nuevo “clip”. Este procedimiento se realizara libre de costo. Usted debe planificar dejar su vehículo en el concesionario para realizar esta labor. El tiempo de reparación dependerá de la agenda de trabajo del concesionario.

¿Que debe usted hacer?

Le urgimos a que llame a su concesionario Hyundai para programar una cita para realizar esta labor lo antes posible.

¿Que hacer si usted otras preguntas?

Si usted tiene alguna dificultad al tener esta reparación realizada, le recomendamos que usted llame al Departamento de Servicio al Cliente de Hyundai de Puerto Rico al 787-999-3333. Si usted todavía no está satisfecho en que hayamos remediado esta situación libre de costo y dentro de un tiempo razonable, puede escribir a la Oficina del Administrador, Administración Nacional de Seguridad de Transito de la Carretera, 1200 New Jersey Avenue, SE., Washington, D.C. 20590, o llame la línea de libres de cargos “Vehicle Safety Hotline” al 1-800-327-4236 (TTY: 1-800-424-9153), o diríjase a la red, a través de la página de <http://www.safecar.gov>.

Le agradecemos su pronta atención en este asunto de seguridad.

Hyundai de Puerto Rico