



Mitsubishi Motors North America, Inc.

6400 Katella Avenue
Cypress, CA 90630
Tel: 714-372-6000
www.mitsubishicars.com

April 22, 2010

Kathleen DeMeter, Esq.
Director, Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave. SE
Washington, D.C. 20590

Subject: Quarterly Campaign Progress Report – 1st Quarter 2010

Dear Ms. DeMeter:

Attached is the Quarterly Campaign Progress Report prepared in accordance with Federal Regulation 573.6 for the calendar quarter January 1 through March 31, 2010 (1st Quarter 2010).

If you have any questions concerning this report, please do not hesitate to contact me directly during normal business hours.

Sincerely,

A handwritten signature in cursive script that reads "Sharon Kaplan".

Sharon Kaplan
Sr. Specialist, Technical Compliance
Mitsubishi Motors North America, Inc.
Telephone: (714) 372-6148
Fax: (714) 934-4202
E-mail: skkaplan@mmsa.com

cc: Kelly Schuler (Email)

Enclosure

MMNA 1st Quarter 2010
Campaign Progress Report

| NHTSA Recall Number | MMNA Recall Number | Campaign Name | Owner Notification Start | Owner Notification End | Total Number of Vehicles Involved | Number Vehicles Inspected and Repaired | Number Vehicles inspected not needing Repair | Vehicles Exported | Vehicles Stolen | Vehicles Scrapped | Notification Undeliverable | Sold or Traded | Quarters Reported |
|---------------------|--------------------|--|--------------------------|------------------------|-----------------------------------|--|--|-------------------|-----------------|-------------------|----------------------------|----------------|-------------------|
| 08V680 | SR-09-001 | Outlander Stop Lamp Switch | 24-Feb-09 | 24-Feb-09 | 19,852 | 14,739 | NA | 0 | 0 | 78 | 627 | 67 | 5 |
| 09V077 | SR-09-002 | Lancer/Outlander Brake Booster Check Valve | 5-May-09 | 5-May-09 | 48,844 | 35,711 | NA | 0 | 0 | 241 | 1,887 | 118 | 4 |
| 09V361 | SR-09-003 | Endeavor Side Air Bag Anchor Bracket | 29-Sep-09 | 29-Sep-09 | 531 | 5 | 416 | 0 | 0 | 0 | 0 | 0 | 3 |
| 09V349 | SR-09-004 | Lancer Ralliart/ Evolution/ Sportback Fuel Return Pipe | 29-Sep-09 | 29-Sep-09 | 7,083 | 4,397 | NA | 0 | 0 | 39 | 384 | 29 | 3 |
| 09V435 | SR-09-005 | Lancer/Lancer Evolution SRS Front Impact Sensor | 27-Nov-09 | 27-Nov-09 | 29,779 | 14,826 | NA | 6 | 2 | 193 | 854 | 74 | 2 |
| 10V066 | SR-10-001 | Galant A/T Oil Cooler Pipe | 22-Mar-10 | 22-Mar-10 | 2,307 | 29 | 102 | 0 | 0 | 1 | 6 | 0 | 1 |