

Recall Bulletin 10420FRV



Revision 1: Added M.Y. 2011 affected units

RECALL BULLETIN:
10420FRV

YEAR(S) AFFECTED:
2010, 2011

PRODUCT(S) AFFECTED:
Bounder Classic,
Encounter

MODEL(S) AFFECTED:
2010 Bounder Classic: 30T, manufactured March 27, 2010 through March 29, 2010;
2010 Encounter: 28MS, 30SA, 32BH; manufactured February 26, 2010 through March 30, 2010;
2011 Bounder Classic: 30T, manufactured May 27, 2010 through June 17, 2010

SUBJECT:
Install new Manufacturer Federal Certification Tag

KEYWORDS:
Manufacturer Federal Certification Tag, label, tire, pressure

ISSUE DATE:
July 2010

© 2010 Fleetwood RV, Inc.

The purpose of this Bulletin is to inform Fleetwood dealers of the need to replace the Manufacturer Federal Certification Tag on certain Bounder Classic and Encounter motor homes.

CONDITION:

Fleetwood RV, Inc., has discovered that on the identified motor homes, the figures related to the front and rear tire pressure, appearing on the Manufacturer Federal Certification Tag, are incorrect. The correct front tire pressure is 95 PSI (655 KPA) and the correct rear tire pressure is 100 PSI (690 KPA).

Read this entire document before proceeding.

CORRECTION:

Retail owners of affected motor homes and dealers holding affected motor homes in inventory will receive a package from Fleetwood containing a new and corrected, **serial number specific**, Manufacturer Federal Certification Tag. Verify eligibility by referring to the affected motor home serial numbers listed at the end of this Bulletin before applying new labels.

Important: Be sure the correct replacement Manufacturer Federal Certification Tag is on-hand before proceeding.

1. Locate the original Federal Certification Tag, adhered to the wall behind the driver's seat.
2. Record any additional weight information (if present) that was written on the original Manufacturer Federal Certification Tag due to the addition of options after the motor home was manufactured. (See Figure 1.) Transfer this information to the new Manufacturer Federal Certification Tag using a black, fine point, permanent marker.




Figure 1

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that: If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."

3. a) If the original Federal Certification Tag is loose or peeling, remove it and discard. Remove any adhesive residue in the application area using a clean shop cloth slightly dampened with isopropyl alcohol.
b) If the original Federal Certification Tag is adhered securely in place, use a black permanent marker to deface it.
4. Peel and tear approximately 1" from the top of the adhesive backing of the new Federal Certification Tag. (This will allow control of the application.) Slowly apply the new Tag directly over the original, using your fingers to smooth down newly-applied areas. (If the original Tag was removed in Step 3a, apply the new Tag in the same location as the original.) Continue to remove backing, working from top to bottom, until the entire tag completely adheres to and covers the original tag.

NOTE: Federal Certification labels have "tamper-proof" edges and are designed to tear if removal is attempted.

PARTS:

Use tag supplied with the Recall mailing. No additional parts are necessary.

TOOLS:

Black, Fine Point, Permanent Marker
Clean Shop Cloth
Isopropyl Alcohol

WARRANTY LABOR ALLOWANCE:

Use Flat Rate Codes:

Recall 10420FRV, Bounder Classic, Encounter, Install New Federal Certification Tag
9226 - 12 0.10 hr. Inspected / Defective/Repaired

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that: If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."

Recall 10420FRV Affected Unit Serial Numbers

2010 Bounder Classic

738TA4405328
738TA4405329

738TA4405330
738TA4405331

2010 Encounter

785MA4405034	785SA4405104	785BA4405128	785MA4405151
785MA4405035	785SA4405105	785BA4405129	785MA4405295
785MA4405036	785SA4405106	785BA4405130	785MA4405296
785MA4405037	785SA4405107	785BA4405131	785MA4405297
785MA4405038	785SA4405108	785BA4405132	785MA4405298
785MA4405039	785SA4405110	785BA4405133	785MA4405299
785MA4405040	785SA4405111	785BA4405134	785MA4405300
785MA4405041	785SA4405112	785BA4405135	785MA4405301
785MA4405042	785SA4405113	785BA4405136	785MA4405302
785MA4405043	785SA4405114	785BA4405137	785MA4405303
785MA4405044	785SA4405115	785BA4405138	785MA4405304
785MA4405092	785BA4405116	785BA4405139	785MA4405305
785MA4405093	785BA4405117	785BA4405140	785MA4405306
785MA4405094	785BA4405118	785BA4405141	785MA4405307
785MA4405095	785BA4405119	785BA4405142	785MA4405308
785MA4405096	785BA4405120	785BA4405143	785MA4405309
785MA4405097	785BA4405121	785BA4405144	785MA4405310
785SA4405098	785BA4405122	785BA4405145	785MA4405311
785SA4405099	785BA4405123	785BA4405146	785MA4405312
785SA4405100	785BA4405124	785BA4405147	785MA4405314
785SA4405101	785BA4405125	785MA4405148	
785SA4405102	785BA4405126	785MA4405149	
785SA4405103	785BA4405127	785MA4405150	

2011 Bounder Classic

738TB4405830
738TB4406105

738TB4406106
738TB4406111

738TB4406112
738TB4406119

738TB4406120
738TB4406127

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that:
If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."