

CERTAIN 2010 MODEL YEAR TRANSIT CONNECT VEHICLES — HEADLINER PUSHPIN REPLACEMENT

OVERVIEW

On some of the affected vehicles, the headliner pushpin at the B-pillar may not absorb sufficient energy to conform to the requirements specified by Federal Motor Vehicle Safety Standard (FMVSS) No. 201 - Occupant Protection in Interior Impact.

SERVICE PROCEDURE

1. Remove the existing headliner pushpins (one per side) located directly above the right and left upper B-pillar trim panels. See Figure 1.
2. Install the revised pushpins.




FIGURE 1

