



Fleetwood RV, Inc.
1010 Commerce Dr.
Decatur, Indiana 46733
P: (800) 322-8216 / www.fleetwoodrv.com

February 9, 2011

Mr. Daniel C. Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Ave, SE
Washington, DC 20590

Re: Noncompliance Report

Dear Mr. Smith:

On February 4, 2011, Fleetwood RV, Inc., determined that a safety defect exists in certain motor homes as listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Reports.

The following is the information required by 49 CFR Part 573:

- This report was prepared on February 9, 2011
 - Fleetwood RV has assigned 110204FRV as an identification code to this recall.
- (1) The affected motor homes were manufactured by the following wholly owned subsidiaries of Fleetwood RV, Inc.

Fleetwood RV, Inc. #44
1031 U.S. 224 E
Decatur, Indiana 46733

The agency should contact the following individual with respect to this recall:

Craig Biazio
National Warranty Manager
Fleetwood RV, Inc.
1010 Commerce Dr., P.O. Box 1007
Decatur, Indiana 46733
Telephone: 260-724-5960
E-mail: craig.biazio@fleetwoodrv.com

The vehicles involved in the recall are certain model year 2010 Fiesta Class A motor homes. These motor homes are identified, non-consecutively, as:
794BA4404309 through 794TA4405720
Manufactured November 5, 2009 through May 24, 2010

- (3) Fleetwood RV reports approximately 76 as the number of model year 2010 Fiesta Class A motor homes with the noncompliance.
- (4) Fleetwood RV estimates that 100% of the affected model year 2010 Fiesta Class A motor homes containing the safety defect.

- (5) On motor homes affected by this recall, the headlights may have been incorrectly wired, resulting in reduced headlight illumination with the headlights on low beam. Inadequate illumination of the low-beam headlights may result in decreased driver's vision, as well as the vehicle's visibility to other drivers, increasing the risk of a crash.
- (6) Not applicable.
- (7) Fleetwood RV began an investigation in November 2010 when reduced low beam headlight output was reported by two dealers. Fleetwood RV is not aware of any accidents or injuries which have resulted from this safety defect.
- (8) Fleetwood dealers will inspect the headlight wiring and if necessary, move the headlight wires' pin terminals to the correct positions on the headlight bulb socket connectors.
- (9) Fleetwood RV intends to conduct a dealer notification by e-mail in February 2011.

Fleetwood RV intends to conduct a customer notification in February 2011.

Fleetwood RV does not foresee any problems with implementing this voluntary recall campaign.
- (10) Copies of subsequent correspondence will be submitted to the NHTSA within five (5) working days of distribution. This correspondence will include:
 - I) Letter of dealer notification
 - II) Letter of customer notification
 - III) Service Bulletin

A draft of these documents will be forthcoming for your review. If additional information is required, please contact Joyce Geels who can be reached by phone at (260) 724-5795 or by e-mail at joyce.geels@fleetwoodrv.com.

Sincerely,



Craig S. Biazio
National Warranty Manager