

Date: 7-28-11

Mr. Claude Harris
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attention: Recall Management Division (NVS-215)
1200 New Jersey Avenue, SE.
Washington, DC 20590.

Re: Defect Information Report
Aftermarket Sunroof (Hollandia 700/600, Hollandia TVS 900)
NHTSA Recall #10E-038

Dear Mr. Harris,

In accordance with 49 CFR § 573, R M Stropp Co, an Authorized Installer for Webasto Product North America, Inc., is submitting the attached Defect Information Report regarding approximately 5 aftermarket sunroof systems it installed on new vehicles prior to the delivery to the original purchaser. This filing relates to NHTSA equipment recall 10E-038.

Please contact me if you have any questions.

Sincerely,
By: Ted Baker

Name (Printed): Ted Baker
Title: Owner

Authorized Installer:
Address: 211 W Erie St
Springfield MO
65807

Telephone: 417 881-8434

Email Address: ted@rmsautomotive.com

49 CFR § 573.6
DEFECT INFORMATION REPORT

Authorized Installer: RM Strapp Co Date: 7-28-11
Address: 211 W. Erie St.
Springfield, MO 65807
Telephone: 417 881-8434

In accordance with 49 CFR Part 573 Defect and Noncompliance Responsibility and Reports and relying upon Webasto Product North America' Inc.'s, Defect Information Report filed on August 10, 2010 (See NHTSA Recall # 10E-038), the above Authorized Installer is providing notification to the National Highway Traffic Safety Administration of the following voluntary recall.

(c)(1) Manufacturer/Brands:

The Hollandia 700 and 600 ("H700/600") series and Hollandia TVS 900 ("H900") series aftermarket sunroof assemblies involved in this recall are manufactured by entities related to Webasto Products North America, Inc. ("WPNA"), divided by model lines as follows:

Hollandia 700/600 Series	Hollandia TVS 900 Series
Webasto S.p.A. (Italy)	Webasto Roof Systems Inc.
Corso Asti 4-14	1757 Northfield Drive
10078 Venaria (TO)	Rochester Hills, MI 48309

The recalled equipment population was sold and distributed in the U.S. market by:

Webasto Product North America, Inc.
15083 North Road
Fenton, MI 48430

Some of the affected aftermarket sunroofs were installed on new motor vehicles prior to delivery to the first owner (e.g., installation at the request of a new motor vehicle dealer) by the above Authorized Installer.

(c)(2) Identification of Potentially Affected Motor Vehicles

(c)(3) Total No. of Vehicles Potentially Affected for Each Group in (c)(2)

The aftermarket sunroof systems at issue are described in Section I of WPNA's Defect Information Report filed on August 10, 2010 (See NHTSA Recall # 10E-038). Attached to this report is a table that contains the make, model, model year and approximate number of units installed by this Authorized Installer on new motor vehicles prior to delivery to the first owner (e.g., installation at the request of a new motor vehicle dealer).

(c)(4) Percentage of Vehicles Estimated to Have the Defect

See Section II.4. of WPNA's Defect Information Report filed on August 10, 2010.

(c)(5) Description of the Defect

See Section III.5. of WPNA's Defect Information Report filed on August 10, 2010.

Cause(s) of the defect or noncompliance condition.

See Section III.5. of WPNA's Defect Information Report filed on August 10, 2010.

Potential consequence(s) of the defect or noncompliance condition.

See Section III.5. of WPNA's Defect Information Report filed on August 10, 2010.

Warnings which can precede or occur.

See Section III.5. of WPNA's Defect Information Report filed on August 10, 2010.

Page 3

The aftermarket sunroof systems at issue are described in Section I of WPNA's Defect Information Report filed on August 10, 2010 (See NHTSA Recall # 10E-038). Attached to this report is a table that contains the make, model, model year and approximate number of units installed by this Authorized Installer on new motor vehicles prior to delivery to the first owner (e.g., installation at the request of a new motor vehicle dealer).

(c)(4) Percentage of Vehicles Estimated to Have the Defect

See Section II.4. of WPNA's Defect Information Report filed on August 10, 2010.

(c)(5) Description of the Defect

See Section III.5. of WPNA's Defect Information Report filed on August 10, 2010.

Cause(s) of the defect or noncompliance condition.

See Section III.5. of WPNA's Defect Information Report filed on August 10, 2010.

Potential consequence(s) of the defect or noncompliance condition.

See Section III.5. of WPNA's Defect Information Report filed on August 10, 2010.

Warnings which can precede or occur.

See Section III.5. of WPNA's Defect Information Report filed on August 10, 2010.