

Volvo Cars of North America, LLC

1 Volvo Drive P.O. Box 914 Rockleigh, NJ 07647 Phone: 201-768-7300 www.volvocars.us

Product Safety & Compliance

**** IMPORTANT VEHICLE RECALL NOTICE **** RECALL REPAIR REQUIRED PRIOR TO CUSTOMER DELIVERY

DATE: March 18, 2011

TO: All U.S. and Canadian Volvo Retailers

RE: Volvo Recall 241 Certain Model Year 2011 S40 & C30 Vehicles

The sale or lease of defective or non-compliant motor vehicles or equipment is prohibited. Vehicles in retailer inventory must be remedied prior to sale. Repair information is attached to this communication.

Volvo Cars of North America, LLC (Volvo) has decided to conduct a voluntary safety recall on a very limited number of model year 2011 S40 and C30 vehicles. Volvo has identified that a crack on the top side of the passenger side support member in the engine compartment, may have developed during the forming process in component production. If present, this crack may have an effect on the front structure and may reduce the crash performance of the vehicle.

The corrective action is to inspect for a crack on the top side of the passenger side support member in the engine compartment per RTJ 24496.

If no crack is found, return the vehicle to the customer. This defect is the result of a component forming process issue in production, and there is no risk of a crack forming in the future.

If the inspection reveals that the vehicle has a crack in the side support member, the vehicle must be taken out of service immediately. Please have the Service Manager contact Volvo Fleet Customer Care at 1-877-283-5338. A new replacement vehicle of equal specification will be provided by Volvo.

RECALL 241 ELIGIBLE VEHICLE LIST

Eligible U.S. Vehicles

YV1672MS4B2541597 YV1672MS9B2541675 YV1672MSXB2541684 YV1672MS7B2541691 YV1672MS6B2541701 YV1672MS6B2542198 YV1672MS0B2542214

Eligible Canadian Vehicles

YV1672MK6B2237574 YV1672MK9B2237584 YV1672MS7B2541688 YV1672MSXB2541958

Eligible Puerto Rico Vehicles

YV1672MSXB2542513 YV1672MS2B2542523

OWNER NOTIFICATION

Owner notification is scheduled to begin immediately by Volvo Customer Service.

PARTS INFORMATION

No parts are required for this recall.

CAMPAIGN REIMBURSEMENT PROCEDURES (LONG FORM APPLICATION) A complete recall information package will be released shortly.

Claim Type: R89208 Cause Code: 02 CSC Code: XW Main OP: 81298


Operation Number	Repair Description	Qty	Labor Time
81298	Inspect Front Side Member	1	0.2

INSPECTION INSTUCTIONS ON NEXT PAGE


		Volvo Car Customer Service
		RTJ Instruction
		No.24496
		March 2011 Issue 01
Title	Side member insp	pection.

1.

Note! Some variation in the illustrations may occur, but the essential information is always correct



Check for cracks



NOT OK

OK