


SAFETY RECALL BLD

Sent to Dealers 5/16/12





Intelligent Power Module Transistor Replacement





GREASE APPLICATION PROCEDURE OUTLINE

- Confirm the grease application surface on the NEW IPM transistor is clean before applying grease
- Confirm all original grease inside the inverter case has been completely removed
- If the correct amount of grease is not applied the the new IPM, inverter failure may occur
- Knead the tubes of grease before application to confirm the grease is properly mixed
















Proceed with reassembly.

