

TMS-NTC-13215
August 30, 2013

Recall Management Division
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, DC 20590

Re: Toyota Safety Recalls 09V-023, 09V-031, 10V-176, 11V-112 and 12V-542 Follow-Up Owner
Notification Letter


To whom it may concern,

Please find attached, for your records, representative copies of the Follow-Up Owner Notification on the following Toyota and Lexus vehicles:

NHTSA campaign ID	Toyota campaign No.	Vehicles Covered
09V-023	90B	Certain 2004 MY Sienna
09V-031	90C	Certain 2006-2007 MY Yaris
10V-176	A0G	Certain 2003 MY Sequoia
11V-112	B0A BLC	2004-2006 MY Highlander and Highlander HV Certain 2004 – Early 2007 RX330, RX350 and RX 400h
12V-542	C0V	Certain 2001-2004 MY Tacoma (2WD except PreRunner)

If you have any questions regarding this matter, please contact me at (310) 468-5316.

Sincerely,



Mark Kubota
Quality Compliance Assistant Manager

Attachments:

- Lexus 11V-112 (BLC) Owner Notification
- Toyota 09V-023 (90B) Owner Notification
- Toyota 09V-031 (90C) Owner Notification
- Toyota 10V-176 (A0G) Owner Notification
- Toyota 11V-112 (B0A) Owner Notification
- Toyota 12V-542 (C0V) Owner Notification



Lexus Division
 Toyota Motor Sales, U.S.A., Inc.
 19001 South Western Avenue
 P.O. Box 2991
 Torrance, CA 90509-2991

URGENT SAFETY RECALL

This is an important Safety Recall.
 The remedy will be performed at
NO CHARGE to you.

**Certain 2004 – 2007 Model Year RX 330/350/400h
 Floor Carpet Cover and Retention Clips
 SAFETY RECALL FOLLOW-UP NOTICE (Replacement Parts Available)**

URGENT

[VIN]

Dear Lexus Customer:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Lexus has decided that a defect, which relates to motor vehicle safety, exists in certain 2004 through 2007 Model Year RX 330/350/400h vehicles. Our records indicate that you own a vehicle that has not yet had this condition corrected.

What is the condition?

In certain 2004 through 2007 model year RX 330/350/400h vehicles, if the forward retention clip used to secure the driver's side Floor Carpet Cover, which is located in front of the center console, is not installed properly, the cover may lean toward the accelerator pedal and interfere with the accelerator pedal arm. If this occurs, the accelerator pedal may temporarily become stuck in a partially depressed position rather than returning to the idle position. An accelerator pedal temporarily stuck in a partially depressed position may increase the risk of a crash.

What is Lexus going to do?

The replacement parts for your vehicle are available. Lexus will replace the Floor Carpet Cover with one of a different shape as well as both forward and rear retention clips.

What should you do?

- Please contact any authorized Lexus dealer and make an appointment as soon as possible to have the Floor Carpet Cover and both forward and rear retention clips of your vehicle replaced at **no charge** to you.
- The replacement of the cover and clips will take approximately 20 minutes. However, depending upon the dealer's work schedule, it may be necessary to make your vehicle available for a longer period of time.

You do not need an owner letter to have this recall completed; however, to assist the dealer in confirming vehicle eligibility, we request that you present this notice at the time of your service appointment.

If you would like to update your vehicle ownership or contact information, you may do so by registering at www.lexus.com/ownersupdate. You will need your full 17-digit Vehicle Identification Number (VIN) to input the new information.

What if you have other questions?

- Your local Lexus dealer will be more than happy to answer any of your questions and set up an appointment to perform the repair.
- You can find additional information and locate a Lexus dealer in your area by going online and visiting www.lexus.com/recall.
- Additional information is also available by contacting the Lexus Customer Assistance Center at 1-800-255-3987 Monday through Friday, 5:00 a.m. to 6:00 p.m., or Saturday 7:00 a.m. through 4:00 p.m. Pacific Time.

If you believe that the dealer or Lexus has failed or is unable to remedy the defect within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E., Washington, D.C. 20590, or call the toll free Vehicle Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to www.safercar.gov.

What if you have previously paid for repairs to your vehicle for this specific condition?

If you have previously paid for repair to your vehicle for this specific condition prior to receiving this letter, please mail a copy of your repair order, proof-of-payment and proof-of-ownership to the following address for reimbursement consideration:

Lexus Customer Assistance, Mail Stop L201, 19001 South Western Avenue, Torrance, CA 90509

Include your name, address, and telephone number(s) in your request. Please allow us 6-8 weeks to process your request.

If you are a vehicle lessor, Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We have sent this notice in the interest of your continued satisfaction with our products, and we sincerely regret any inconvenience this condition may have caused you.

Thank you for driving a Lexus.

Sincerely,

Lexus Division,
 TOYOTA MOTOR SALES, U.S.A., INC.

Spanish translation on back side
 Traducción en español en el lado inverso