



NHTSA Campaign Number: 11V-232

Dear Sir/Madam,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

MV Agusta Motor SpA has decided that a defect which relates to motor vehicle safety exists in certain MY 2010 model F4 MV Agusta motorcycles. We are therefore conducting a voluntary safety recall.

YOUR VEHICLE IS AFFECTED

MV Agusta has determined that on the rear subframe (P/N 8000B5268) of the affected F4 motorcycles, the upper fixture points may not be sufficiently robust, which may result in the subframe cracking and failing local to the fixture points during use. If this were to occur, the stability of rider and passenger could be compromised, thereby causing the risk of a crash.

WARNINGS which can precede breakage:

If you detect a crack local to the fixture points, transport your motorcycle to your MV Agusta dealer. Do not ride it.

MV Agusta is taking the following measures to remedy the defect:

- Notifying affected MV Agusta F4 owners.
- Conducting a voluntary recall so that affected vehicles will be inspected and repaired by a MV Agusta dealer, free of charge.
- The recall will involve installing, free of charge, a reinforcement support kit for the rear subframe (P/N 8000B5361). This support provides the necessary robustness.
- The earliest date that a MV Agusta dealer can remedy the defect is 4 April 2011. We ask that you make arrangements with your MV Agusta dealer without delay. Call your dealer as soon as possible. Your MV Agusta dealer will need approximately 1 hour to install the support kit.

IT IS IMPERATIVE TO COMPLETE THE RECALL AS SOON AS POSSIBLE.

Please note that you may submit a complaint to the National Highway Traffic Safety Administration, 1200 New Jersey Ave SE. Washington, DC 20590, or you may call the toll free Auto Safety Hotline at 1-888- 327-4236 (TTY 800 424 9153) or go to www.safercar.gov , if you believe that:

- MV Agusta or your designated repair facility has failed to or is unable to remedy the defect without charge.
- MV Agusta or your designated repair facility has failed to or is unable to remedy the defect without charge within a reasonable time, which is not longer than 60 days after you tender the vehicle to the designated repair facility.

Any Lessor that receives this notification must send a copy of this notice to the Lessee.

Any Dealer that receives this notification must send a copy of this notice to the Customer.

MV Agusta will reimburse an owner who has already incurred costs to obtain a remedy for the problem addressed by this recall (other than caused by accident or abuse) done on affected vehicles prior to the recall.





NHTSA Campaign Number: 11V-232

We apologize for this inconvenience, however we have taken this action in the interest of your safety and continued satisfaction with our products. If you have any questions, please contact:

MV Agusta USA, LLC
2300 Maryland Road
Willow Grove, PA 19090-4193
Phone: 215-830-3300
Office Fax: 215.830.3301

If you have sold your vehicle or have taken it out of service, please complete the enclosed reply sheet and return it to **MV Agusta USA, LLC** or use the following email address info@mvagusta.it

Your cooperation is appreciated.
Sincerely yours,

MV Agusta Customer Service

.....
To MV Agusta Customer Service

Motorcycle VIN:

Motorcycle cannot be checked because it has been

- scrapped**
- stolen**
- sold to a domestic buyer**
- sold to an overseas buyer**

to new address:

Name: _____

First name: _____

Street: _____

Zip code: _____ **Town:** _____

Country: _____

Date / signature:

