



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

CITY OF GASTONIA  
PO BOX 1748  
GASTONIA, NC 28053-1748

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

CITY OF RICHMOND HEIGHTS  
1330 S BIG BEND BLVD  
RICHMOND HEIGHTS, MO 63117-2202

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

ONTARIO COUNTY  
20 ONTARIO ST  
CANADAIGUA, NY 14424

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

TOWN OF VAIL  
75 FRONTAGE RD W  
VAIL, CO 81657

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

MACOMB COUNTY ROAD COMMISSION  
117 S GROESBECK HWY  
MOUNT CLEMENS, MI 48043

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

COLUMBIA COUNTY  
PO BOX 324  
HUDSON, NY 12534

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



Subsidiary of Federal Signal Corporation

1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

MACOMB COUNTY ROAD COMMISSION  
117 S GROESBECK HWY  
MOUNT CLEMENS, MI 48043

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



Subsidiary of Federal Signal Corporation

1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

DALLAS CITY OF TEXAS  
1500 MARILLA ST  
ROOM 4BN  
DALLAS, TX 75201

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

DALLAS CITY OF TEXAS  
1500 MARILLA ST  
ROOM 4BN  
DALLAS, TX 75201

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

ALL AMERICAN WASTE  
15 MULLEN RD  
ENFIELD, CT 06082

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



Subsidiary of Federal Signal Corporation

1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

FARIS MACHINERY CO  
772 VALLEY CT  
GRAND JCT, CO 81505

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



Subsidiary of Federal Signal Corporation

1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



Subsidiary of Federal Signal Corporation  
1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

SUNY BINGHAMTON  
PO BOX 6000  
BINGHAMTON, NY 13902

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

JEFFERSON COUNTY PUBLIC WORKS  
PO BOX 100  
HILLSBORO, MO 63050

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



Subsidiary of Federal Signal Corporation

1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

CITY OF HIBBING  
1425 E 23<sup>RD</sup> ST  
HIBBING, MN 55746

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

PUBLIC WORKS EQUIPMENT & SUPPLY  
3405 WESTWOOD INDUSTRIAL  
MONROE, NC 28110

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

BELL EQUIPMENT CO  
78 NORTHPOINTE DR  
LAKE ORION, MI 48359

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

May 30, 2011

HANFORD RESERVATION  
2355 STEVENS DR  
RICHLAND, WA 99354

Elgin Megawind MX Sweeper serial numbers: MX3002D, MX3006 through MX3021, MX3025, and MX3026

Dear Elgin Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### REASON FOR RECALL

Elgin Sweeper has decided that a defect which relates to motor vehicle safety exists in certain Megawind sweepers with Tier III John Deere auxiliary engines manufactured from February 2010 through April 2011. These Megawind sweepers are equipped with a radiator fan mounted to the auxiliary engine crankshaft. Under heavy operating conditions and high auxiliary engine RPMs, the fans may fail. If the fan fails then the fan blades will separate from the base of the fan and the blades or debris from the blades could leave the fan housing. If this condition occurs, then a person performing a repair could be injured. In the event of a failure, it is possible for a small piece of fan debris to exit the vehicle in 2 openings in the exterior of the vehicle. Your Elgin Megawind Street Sweeper will need to be repaired to prevent this condition.

#### WHAT WE WILL DO

A safety recall has been issued for Elgin Megawind sweepers with John Deere Tier III auxiliary engines. Elgin will repair this defect free of charge. We will install a new radiator fan on a belt-driven pulley and new mounting hardware.

#### WHAT YOU SHOULD DO

Please contact your Elgin Sweeper dealer as soon as possible to arrange a service date so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. It will take approximately 24 hours to complete this repair. Due to scheduling or other conditions, the repair could take longer than 24 hours to complete the repair. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Elgin Sweeper Customer Service Department at 1-877-DIAL-ESG (1-877-342-5374).

Your Elgin Sweeper dealer is best equipped to obtain parts and provide service to ensure that your Megawind sweeper is corrected as promptly as possible. If, however, you take your sweeper to your dealer on the agreed service date, and



1300 West Bartlett Road  
Elgin, IL 60120-7529  
877-342-5374

---

they do not remedy this condition within fourteen (14) days of that date, we recommend you contact Elgin Customer Service by calling 1-877-DIAL-ESG (1-877-342-5374).

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,

Mario Martinez  
Service Manager  
Elgin Sweeper

cc: Elgin Dealer