

Publish Date: July 19, 2011
From: Technical Service
Expiration Date: August 02, 2011

DCSnet Message
Important

Subject: Delivery Stop X5 xDrive35d Recall Campaign 11V-332:
Replace Alternator Drive Belt Tensioner

To: BMW Service Managers, Shop Foremen, and Technicians

Subject: Delivery Stop X5 xDrive35d Recall Campaign 11V-332: Replace Alternator Drive Belt Tensioner

Model Year 2011 X5 xDrive35d (E70 diesel) vehicles produced between 3/31/11 and 5/19/11 are the subject of a safety recall.

The issue involves the engine drive belt tensioner. A crack could develop in the housing and lead to the failure of the tensioner, which can result in a loss of the power steering assist. Manual steering capability would still be retained. SI B11 06 11 will be posted on TIS shortly; this recall involves just 968 vehicles.

Please do not over-order replacement parts. Over-ordering will cause backorders and repair delays. Please only order what is needed for vehicle inventory at this time.

Technical Service

Attachments:

No Attachments

Recipients:

BMW Passenger Cars, Service, All Regions, All Areas, All Departments, All Personnel
BMW Passenger Cars, Part Sales, All Regions, All Areas, All Departments, All Personnel