

National Highway Traffic Safety Administration (NHTSA)
Vehicle Safety Recall Quarterly Progress Report for Fleetwood RV, Inc.
Quarterly Report from January 1, 2012 through March 31, 2012
Report Date - April 27, 2012 / Report Author - Julie Jones (260) 724-5716

# of Quarters Reported	NHTSA Recall #	FRV Recall #	Date of 1st Mailing	Date of 2nd Mailing	Date of 3rd Mailing	Total # Vehicles Involved	Total # Inspected & Remedied	Total # Inspected & Not Requiring Remedy	Total # Exported	Total # Inspected / Defective / Owner Declined	Total # Unable to Notify	Description of Recall
6	10V-539	N/A	11/15/10	N/A	N/A	83	0	23	1	0	0	ATWOOD Series 35 Range-Oven recall. A potential exists for a small fracture within the line delivering gas to the oven cavity burner. Such a fracture may cause propane to leak from the line. A propane leak in the presence of an ignition source could result in a fire and/or explosion causing property damage and/or personal injury. All notifications are being administered by Atwood. Note: 16 items were returned from inventory or remedied prior to sale.
6	10V-577	101105FRV	12/10/10	03/11/11	06/10/11	84	69	0	10	1	0	MY 11 Terra - Headlights not in compliance with Federal Motor Vehicle Safety Standard No. 108, "Lamps, Reflective Devices, and Associated Equipment." Note: Nine (9) of the units originally involved were at Canadian dealerships; they were reported to Transport Canada. One (1) unit was previously misreported as Inspected & Not Requiring Remedy, corrected to Inspected/Defective/Owner Declined.
5	11V-009	110103FRV	03/02/11	06/17/11	09/22/11	11	9	0	1	0	0	Propane tank inspection and relocation
5	11V-074	N/A	N/A	N/A	N/A	88	49	0	14	0	0	NORCOLD 1200-series refrigerators. The sensing algorithm or thermal switch designed to shut off power to the refrigerator when high temperatures are detected may not activate in sufficient time to prevent a fire. All notifications are being administered by Norcold.
5	11V-090	110204FRV	03/18/11	06/20/11	09/16/11	68	55	3	0	0	0	MY 10 Fiesta - Inspection/Correction of Headlight Wiring
5	11V-192	110318FRV	06/10/11	09/09/11	12/16/11	98	53	28	2	0	0	MY 2011 Discovery, Providence, Revolution LE - ITC Brand Interior Dimmer Switch Replacement
4	11V-298	110520FRV	07/08/11	10/14/11	01/18/12	703	362	222	2*	0	1	Wire Harness Routing on Class A Units Built on Ford F53 Chassis MY 2011 Bounder, Bounder Classic, Storm, Terra, Southwind and MY 2012 Southwind and Bounder (*Includes 1 exported - Germany)
3	11V-383	110715FRV	08/25/11	11/23/11		220	92	5	7*	2	3	Federal Certification Tag - Incorrect Intermediate and Rear Tire KPA Values (*Includes 3 exported - UK)
3	11V-399	110728FRV	08/25/11	11/29/11		408	84	172	4*	1	1	MY 10-11 Class A Motor Homes - Siemens 15-20-30 Amp 120-volt Circuit Breakers. Note: The Total # Vehicles Involved was updated per the Amendment filed December 16, 2011 - 1st Mailing for additional 49 units was 12-21-11. (*Includes 1 exported - Poland)