

CERTAIN 2011 MODEL YEAR F-650/750 EQUIPPED WITH AIR BRAKES AND TRAILER ABS OR TRACTOR PACKAGE — ABS MODULE REPLACEMENT

OVERVIEW

Affected vehicles were built with the Power Line Carrier (PLC) parameter disabled, resulting in no illumination of the trailer ABS warning lamp to the vehicle operator if a trailer ABS fault occurs. Before demonstrating or delivering any of the vehicles involved in this recall, dealers are to replace the ABS module.

SERVICE PROCEDURE

1. Replace the ABS module. For additional information, refer to the WSM, Section 206-09B.

NOTE: Vehicles affected by this recall will be equipped with either a standard or premium ABS module. See Figure 1.



FIGURE 1

