

## CERTAIN 2007 MODEL YEAR FIVE HUNDRED AND MONTEGO VEHICLES — FUEL TANK REPLACEMENT

### OVERVIEW

In some of the affected vehicles, the fuel tank may have an improper weld between the plastic fuel tank and the plastic fuel filler inlet device. In the event of a severe rear impact to the vehicle, the weld may not provide the expected strength and could result in a fuel leak. A sufficient fuel leak in the presence of an ignition source may result in a fire. Dealers are to replace the fuel tank in the affected vehicles.

### SERVICE PROCEDURE

1. Replace the fuel tank. For additional information, refer to WSM Section 310-01.

**NOTE:** Do not discard the exhaust system Torca® clamp, it may be reused during reassembly.

**NOTE:** For AWD vehicles, do not discard the driveshaft flange bolts. During reassembly coat the threads of the original bolts with threadlock and sealer.

