

U.S. Department of Transportation

National Highway Traffic Safety Administration

July 27, 2012

Mr. David Robertson Group Manager, Environmental, Safety and Powertrain Engineering Mazda North American Operations 1500 Enterprise Drive Allen Park, MI 48101-2053 NVS-215KS 12V-357

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Speed Control Cable Connector Interference

Dear Mr. Robertson:

This letter serves to acknowledge Mazda North American Operations's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MAZDA/TRIBUTE/2001-2006,2008

Mfr's Report Date: July 26, 2012

NHTSA Campaign Number: 12V-357

Components:

ENGINE AND ENGINE COOLING VEHICLE SPEED CONTROL:CABLES

Potential Number of Units Affected: 217,500

Problem Description:

Mazda is recalling certain model year 2001 through 2006, and 2008, Tribute vehicles equipped with 3.0L V6 engines and speed control. Inadequate clearance between the engine cover and the speed control cable connector could result in a stuck throttle when the accelerator pedal is fully or almost-fully depressed. This risk exists regardless of whether or not speed control (cruise control) is used.

Consequence:

A stuck throttle may result in very high vehicle speeds and make it difficult to stop or slow the vehicle, which could cause a crash, serious injury or death.

Remedy:

Mazda will notify owners, and dealers will repair the vehicles by increasing the engine cover clearance, free of charge. The safety recall is expected to begin on, or before, August 6, 2012. Remedy parts are expected to be available in mid-August 2012. Until then dealers will disconnect the speed control cable as an interim remedy, if parts are not available at the time of an owner's service appointment. Owners may contact Mazda Customer Assistance Center at 1-800-222-5500, option #6.

Notes:

Mazda's recall campaign number is 6812G. Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



This recall is the subject of an investigation, PE12-019, being conducted by the Office of Defects Investigation.

We have received Mazda's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, October 31, 2012.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

