

U.S. Department of Transportation

National Highway Traffic Safety Administration

December 11, 2012

NVS-215KS

12V-573

1200 New Jersey Avenue SE Washington, DC 20590

Mr. Jay Joseph Senior Mgr, Product Regulatory Office Honda (American Honda Motor Co.) 1919 Torrance Blvd. Torrence, CA 90501

Subject: Ignition Interlock may Deform Allowing Rollaway

Dear Mr. Joseph:

This letter serves to acknowledge Honda (American Honda Motor Co.)'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

ACURA/MDX/2003-2006 HONDA/ODYSSEY/2003-2004 HONDA/PILOT/2003-2004

Mfr's Report Date: December 10, 2012

NHTSA Campaign Number: 12V-573

Components:

ELECTRICAL SYSTEM:IGNITION:SWITCH

Potential Number of Units Affected: 807,161

Problem Description:

Honda is recalling certain model year 2003 and 2004 Pilot and Odyssey and 2003 through 2006 Acura MDX passenger vehicles manufactured from November 26, 2001, through August 30, 2006. The interlock lever of the ignition switch may deform, which can allow the interlock function of a vehicle with an automatic transmission to be defeated.

Consequence:

Removal of the ignition key when the gear selector of a vehicle with an automatic transmission has not been shifted to the park position can allow the vehicle to roll away, increasing the risk of a crash.

Remedy:

Honda will notify owners and instruct them to take their vehicle to a Honda or Acura dealer. The dealer will install an updated shift interlock lever and, if necessary, replace the ignition switch, free of charge. The recall is expected to begin on, or about, February 7, 2013. Owners may contact Honda at 1-800-999-1009.

Notes:

Honda's recall campaign numbers are S73 and S74. Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



This recall was the subject of a Preliminary Evaluation, PE12-026, conducted by the Office of Defects Investigation.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

