



903 South Main Street • P.O. Box 460 • Middlebury, IN 46540 • (574) 825-0608 • Fax (574) 825-0572

April 27, 2012

Associate Administrator for Enforcement
Department of Transportation
National Highway Traffic Safety Administration
Office of Enforcement NVS-200 Room W45-306
1200 New Jersey Avenue S.E.
Washington, DC 20590

Dear Sir or Madam:

Pursuant to 49 CFR Part 573, Jayco, Inc. ("Jayco" or the "Company") is submitting this report to NHTSA concerning a recall campaign, which is being voluntarily initiated. Specific information is as follows:

573.6(c)(2)

Affected vehicles are 2012 Jay Flight Bungalow Travel Trailers.

The affected vehicles were manufactured between March 19, 2012 and March 27, 2012.

The recall population was determined from the manufacturing records for the Company's manufacturing plant in Middlebury, Indiana, which produced the affected recreational vehicles.

573.6(c)(3)

A total of 66 vehicles are subject to this recall. Specific Vehicle Identification Numbers (VIN) are as follows:

Model year 2012 vehicles with a starting VIN of 1UJB0BV0C1 [REDACTED] and ending with 1UJB0BVXC1 [REDACTED].

573.6(c)(4)

Jayco is recalling 100 percent of the affected vehicles identified in the scope.

573.6(c)(5)

Jayco has decided that certain 2012 Jay Flight Bungalow Travel Trailers fail to conform to the requirements of Federal Motor Vehicle Safety Standard No. 120, "Tire selection and rims and motor home/recreation vehicle trailer load carrying capacity information for motor vehicles with a GVWR of more than 4,536 kilograms (10,000 pounds)". The load range of the tire as indicated on the Federal ID Label is incorrectly identified as D when it should be E. Also, the cold tire inflation pressure should be 80 psi (552 kPa) but instead 65 psi (448 kPa) is printed on the labels. All other information on the Federal ID Label is stated correctly.

573.6(c)(6)

On April 9, 2012, Jayco's Customer Service Department received an email inquiry about the Certification label information on two units just delivered to a dealer. Upon investigation the error was identified. There have been no other complaints or any warranty claims related to this concern.

573.6(c)(8)

The remedy for the affected vehicles will involve removing and replacing the Federal ID Label with a correct label.

Copies of the repair instructions, dealer notification letters, and owner letters will be provided to the agency within 10 business days. Jayco is contacting all dealers and retail owners of the affected vehicles. Upon notification Jayco is prepared to begin dealer notification within 5 business days after approval, and to owner's ten business days subsequent to dealer notification.

Thank you for your assistance,

A handwritten signature in cursive script that reads "Joseph J. Resil". The signature is written in black ink and is positioned below the text "Thank you for your assistance,".

Sincerely,

Joe Resil
Regulatory Compliance Manager