



903 South Main Street • P.O. Box 460 • Middlebury, IN 46540 • (574) 825-0608 • Fax (574) 825-0572

July 23, 2012

Associate Administrator for Enforcement
Department of Transportation
National Highway Traffic Safety Administration
Office of Enforcement NVS-200 Room W45-306
1200 New Jersey Avenue S.E.
Washington, DC 20590

Dear Sir or Madam:

Pursuant to 49 CFR Part 573, Jayco, Inc. (“Jayco” or the “Company”) is submitting this report to NHTSA concerning a recall campaign, which is being voluntarily initiated. Specific information is as follows:

573.6(c)(2)

Affected vehicles are 2007 Jayco Greyhawk Class C Motorhomes; 2008 & 2010 Seneca Class C Motorhomes; 2009 & 2011 Eagle Fifth-wheels; 2010 Recon Fifth-wheels; 2008, 2009, and 2010 Designer Fifth-wheels.

The affected vehicles were manufactured between June 15, 2006 and August 13, 2010.

The recall population was determined from the manufacturing records for the Company’s manufacturing plant in Middlebury, Indiana, which produced the affected recreational vehicles.

573.6(c)(3)

A total of 908 vehicles are subject to this recall. Specific Vehicle Identification Numbers (VIN) are as follows:

Model year 2007 - 2010 vehicles with a starting VIN of 1GBE5U1G06F and ending with 1UJCJSCVXA1 .

573.6(c)(4)

Jayco is recalling 100 percent of the affected vehicles identified in the scope.

573.6(c)(5)

Jayco has decided that certain 2007 Jayco Greyhawk Class C Motorhomes; 2008 & 2010 Seneca Class C Motorhomes; 2009 & 2011 Eagle Fifth-wheels; 2010 Recon Fifth-wheels; 2008, 2009, and 2010 Designer Fifth-wheels may have an improper electrical connection at the buss bar on the affected transfer switches. This improper connection may lead to overheating and melting of the transfer switch.

573.6(c)(6)

Jayco decided to conduct this recall following an internal investigation subsequent to receiving VOQ 10461090. Jayco is not aware of any property damage, injuries or accidents related to this issue. Between 2008 and 2012, Jayco received 20 complaints and/ or claims related to melting, burning, or smoking wires or connections inside the 50 amp transfer switches. All of those 20 complaints and/or claims were resolved by having the transfer switch replaced. Jayco installed a total of 6153 of the 50 amp transfer switches (0.33% incident rate).

573.6(c)(8)

The remedy for the affected recreational vehicles is to replace the transfer switch.

Copies of the repair instructions, dealer notification letters, and owner letters will be provided to the agency within 10 business days. Jayco is contacting all dealers and retail owners of the affected vehicles. Upon notification Jayco is prepared to begin dealer notification within 5 business days after approval, and to owner's ten business days subsequent to dealer notification.

Thank you for your assistance,

A handwritten signature in black ink that reads "Joseph J. Resil". The signature is written in a cursive style with a large, prominent initial "J".

Sincerely,

Joe Resil
Regulatory Compliance Manager