

RECEIVED

By Recall Management Division at 8:28 am, Feb 11, 2013

12V-573
(1 page) Amended

HONDA

American Honda Motor Co., Inc.
1919 Torrance Boulevard
Torrance, CA 90501-2746
Phone (310) 783-2000

February 5, 2013

Ms. Nancy Lewis
Associate Administrator for Enforcement
NATIONAL HIGHWAY TRAFFIC SAFETY
ADMINISTRATION
Attn: Recall Management Division (NVS-215)
1200 New Jersey Avenue, SE
Washington, DC 20590

**Re: Recall Notification
2003-2004 Honda Pilot and Honda Odyssey
2003-2006 Acura MDX
Ignition Interlock**

Dear Ms. Lewis:

On December 3, 2012 Honda Motor Co., Ltd. (HMC) determined that a potential defect relating to motor vehicle safety exists in the ignition interlock of certain 2003-2004 model year Honda Pilot and Honda Odyssey automobiles and 2003-2006 model year Acura MDX automobiles, and we provided notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Reports on December 10, 2012.

Today, we are updating defect remedy.

573.6(c)(8)(i)

Program for remedying the defect:

The owners of all affected vehicles will be contacted by mail and asked to take their vehicle to a Honda or Acura automobile dealer. The dealer will install an updated shift interlock lever and, if necessary, replace any necessary part of the ignition switch, free of charge.

Sincerely,

AMERICAN HONDA MOTOR CO., INC.



Jay Joseph
Senior Manager
Product Regulatory Office

JWJ:nis