

**\*\* ADVANCED TECHNICAL INFORMATION NOTICE \*\***

Date: January 9, 2012  
To: Mitsubishi Motors Service Managers  
RE: Safety Recall Campaign Notification (12V-001)  
TIN NO. SR-001



AFFECTED VEHICLE: 2012 OUTLANDER SPORT

Mitsubishi Motors North America is recalling 21 model year 2012 Outlander Sport vehicles manufactured from November 9, 2011 – December 16, 2011. These vehicles may fail to comply with a requirement of Federal Motor Vehicle Safety Standard No. 108, “Lamps, Reflective Devices, and Associated Equipment.” The turn signal levers in these 21 units may not auto cancel. If that occurs, a following or oncoming driver may receive inaccurate indications of the vehicle operator’s intended maneuvers thereby increasing the risk of a crash.

It is a violation of Federal law for a Dealer to deliver a new motor vehicle until this noncompliance is remedied.

Since no vehicles have been retailed to customers with this potential condition, no Recall Bulletin or Owner letters will be prepared. You may receive some comments from customers concerning this matter as this information was posted on the NHTSA website on January 6, 2012.

The remedy for this issue was to inspect the operation of the turn indicator self-cancel function and if found inoperative, to replace the turn signal assembly.

Should you have any additional questions concerning this matter, please contact your Zone office for additional information.