

Technical Journal



TITLE:

**Recall 257: Supplemental Restraint System (SRS)
Control Unit Replacement**

REF NO:
TJ 26809

ISSUING DEPARTMENT:
Technical Service

CAR MARKET:
United States

PARTNER:
3 US 7510 Volvo Cars North America

ISSUE DATE:
YEAR MONTH DAY
2012 09 18

FUNC GROUP:
8800

FUNC DESC:
Interior equipment

Page 1 of 1

“Fixed Right — First Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
134							2013-2013		-	0-0
156							2013-2013		-	0-0

CSC Customer Symptom Codes

Code	Description
XW	Service action/Recall/Service action/Recall

DTC Diagnostic Trouble Codes

Text

Volvo Cars of North America, LLC (Volvo) has decided to conduct a voluntary safety recall on a limited number of model year 2013 S60 and XC60 vehicles.

A total of 9 U.S. vehicles are affected. Volvo has contacted the retailers with the affected vehicles and requested that they are quarantined until repaired.

The corrective action is to replace the SRS Control Unit. This procedure is found by following this path in VIDA: Information->Repair->Removal, Replacement and Installation->884->Airbag supplemental restraint system.