

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: M5, M6 Oil Pump Recall Repair Instructions
Date: Tuesday, October 02, 2012 10:36:12 AM

Publish Date: October 02, 2012
From: Technical Service
Expiration Date: October 09, 2012

DCSnet Message 
Important













Subject: **M5, M6 Oil Pump Recall Repair Instructions**

To: All BMW Service Managers, Shop Foremen, Technicians

Centers which have received parts for the S63TU Oil Pump recall to address critical customer cases should refer to the attached repair instructions. The current ISTA version (2.32) may not contain all necessary instructions. An online update to 2.33 is scheduled for Friday, October 5.

Sincerely,

Technical Service

Attachments:  [REP-REP-RAF1031-3111040\[80ed9f57\].pdf](#)  [REP-REP-RAF1011S63TU-1141000\[80ed9f56\].pdf](#)  [REP-REP-RAF1011S63TU-1113020\[80ed9f55\].pdf](#)  [REP-REP-RAF0751-5147490\[80ed9f54\].pdf](#)  [AZD-AZD-AZDMUC3110-F0X\[80ed9f53\].pdf](#)  [AZD-AZD-AZDMUC1141-S63TU\[80ed9f52\].pdf](#)  [AZD-AZD-AZDMUC1113-S63TU\[80ed9f51\].pdf](#)  [REP-REP-RAF1031-3111040\[80ed9f57\].pdf](#)  [REP-REP-RAF1011S63TU-1141000\[80ed9f56\].pdf](#)  [REP-REP-RAF1011S63TU-1113020\[80ed9f55\].pdf](#)  [REP-REP-RAF0751-5147490\[80ed9f54\].pdf](#)  [AZD-AZD-AZDMUC3110-F0X\[80ed9f53\].pdf](#)  [AZD-AZD-AZDMUC1141-S63TU\[80ed9f52\].pdf](#)  [AZD-AZD-AZDMUC1113-S63TU\[80ed9f51\].pdf](#)

Recipients: BMW Passenger Cars, CC-RegionalTechEngineers
BMW Passenger Cars, All Offerings, All Regions, All Areas, Service, Service Manager