

GM CUSTOMER CARE AND AFTERSALES
DCS3326
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 28, 2014

Subject: 12212A – Noncompliance Recall
Turn Signal Lamp Outage Indicator Not Working
Customer Letter Added

Models: 2011-2013 Buick Regal and 2013 Chevrolet Malibu Equipped with
Halogen Headlamps (TT4/T4A)

To: All Buick and Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

This bulletin has been revised to include a copy of the customer letter and to extend the customer reimbursement period to September 30, 2015. Please discard all copies of bulletin 12212.

Customer Letter Mailing

The customer letter mailing will begin on September 12, 2014.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES