



# MOLLY CORPORATION

Manufacture & Sales of MOLLY TROLLEY  
60 Willie Hill Road P.O. Box 1799  
WELLS, MAINE 04090  
(207) 646-5908 FAX (207) 646-6497

## OWNER RECALL NOTICE

**DATE:** September 4, 2012

**FROM:** Molly Corporation  
60 Willie Hill Road  
PO Box 1799  
Wells, ME 04090

**TO:** Boston Trolley Tours, LLC  
Charlestown, MA 02129  
100 Terminal Street

**Vehicle Identification Numbers:** 4UZAB0DT1ACAT5082

Lift Information: NVL 917IB-2 DA-00529 66 14BI  
Braun NHTSA Recall Number: 12E002

**Subject:** Molly Corporation /Braun wheelchair lift series AA through DA Century and Vista 2  
**NHTSA Recall # 12E002**

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

### REASON FOR THIS RECALL

Molly Corporation / Braun Corporation have decided that a defect which relates to motor vehicle safety exists in certain (series AA through DA) Century and Vista 2<sup>nd</sup> generation Dual Parallel Arm model wheelchair lifts manufactured from November, 2006 to September, 2010). The lifts may develop or exhibit a defect related to the outer rollstop latch. This defect may result in a passenger falling from the elevated lift platform and being injured or killed.

#### Affected Vehicle Models:

<u>Model</u>	<u>Model Years</u>
Stadium Molly Trolley	2010

## WHAT WE WILL DO

**Your lift, identified above, is affected.** To correct this condition, please contact your local authorized Braun Dealer and schedule an appointment. Federal law requires any lessor who receives a notification of a determination of a safety-related defect or noncompliance pertaining to any leased motor vehicle shall send the notice to the lessee within 10 days.

The work will take less than one hour to complete. However, additional time may be required depending on your inspection and their shop schedule.

Please bring this Owner Notification Form with you at the time of your appointment and give it to your dealer. This form identifies the lift and the service that is required. Once again, an approved Braun service technician will perform the compliance retrofit.

If you have any problem obtaining the needed repair, or wish to schedule service with an approved Braun technician, please contact The Braun Customer Experience Group at 1-800-488-0359. A Braun Product Support representative will arrange for prompt attention to your lift.

If Molly Corporation fails or is unable to remedy this potential defect without charge and within a reasonable period of time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Your safety and satisfaction with your Molly Corporation product are important to us and we regret any inconvenience to you.

Sincerely,



Jamie Bradish  
Molly Corporation