



---

**NISSAN NORTH AMERICA, INC.**

Corporate Headquarters  
One Nissan Way  
Franklin, TN 37067

Mailing Address: P.O. Box 685001  
Franklin, TN 37068-5001

Telephone: 615.725.3111

August 26, 2013

Ms. Jennifer Timian  
Recall Management Division (NVS-215)  
Office of Defects Investigation  
National Highway Traffic Safety Administration  
1200 New Jersey Ave, S.E.  
Washington, D.C. 20590

Dear Ms. Timian,

In accordance with campaign reporting requirements, the June 2013 quarterly reports are attached. The campaigns and reporting quarters are as follows:

<u>Campaign</u>	<u>Campaign Number</u>	<u>Quarter Report</u>
NV Plate Lock Clip	13V-095	1
NV Titan Brake Shift Lock	13V-094	1
Occupant Classification System (OCS)	13V-069	1
Sentra Fuel Tank	13V-068	2
Altima Transverse Link Bolt	12V-494	3
Frontier Pathfinder Xterra Front Wheel Hub	12V-462	3
JX Fuel Transfer Tube	12V-398	4
Juke Seatback Striker	12V-328	4
Titan Armada Certification Label	12V-143	5
Titan Tire Placard	12V-102	5
M45 Fuel Gauge Inaccuracy	12V-088	5
Quest Fuel Tank	12V-076	5
Juke QX M Fuel Pressure Sensor	12V-069	5
Q45 Side Air Bag	12V-079	6
Rogue Murano TPMS	12V-068	6
Versa Altima Curtain Air Bag	12V-055	6
Versa AT Shifter	12V-032	6
VQ VK Engine Oil Cooler	11V-592	6
Sentra Battery Terminal	11V-579	6
Juke Air Inlet Tube	11V-583	6

<b>QUARTERLY REPORT</b>						
<b>CAMPAIGN NUMBER 12V-068</b>						
<b>ROGUE MURANO TPMS P7250</b>						
	1st QTR.	2nd QTR.	3rd QTR.	4th QTR.	5th QTR.	6th QTR.
OWNER NOTIFICATION BEGAN	N/A*					
OWNER NOTIFICATION COMPLETED	N/A*					
REPORT DATE	3/31/2012	6/30/2012	9/30/2012	12/31/2012	3/31/2013	6/30/2013
NUMBER OF VEHICLES IN THE CAMPAIGN	2,983	2,983	2,983	2,983	2,983	2,983
NUMBER INSPECTED AND REPAIRED	2,983	2,983	2,983	2,983	2,983	2,983
NUMBER INSPECTED--REPAIRS UNNECESSARY	N/A	N/A	N/A	N/A	N/A	N/A
NUMBER OF VEHICLES UNREACHABLE	0	0	0	0	0	0
MEMO-NUMBER EXPORTED	0	0	0	0	0	0
MEMO-THEFT	0	0	0	0	0	0
MEMO-SCRAPPED	0	0	0	0	0	0
MEMO-FAILED TO RECEIVE NOTIFICATION	0	0	0	0	0	0
*Note: No owner notification required. All vehicles were remedied at the dealer. None of the affected vehicles had been retailed without first having their TPMS system activated.						