

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.7

Report Date 2013-10-29
Reporting Quarter Q3 2013

Date in (yyyy-mm-dd) format

Report Author Dominique Gagnon
Phone 418-831-5432 x 235
E-mail dominique.gagnon@volvo.com

								Safety Recall Quarterly Report ...		Total Number of Vehicles/Pces of Equipment Involved			Total Number Inspected & Remedied			Completion (%), per country			Total Number Inspected & NOT REQUIRING REMEDY	Vehicles determined to be Unreachable	For internal use only: Nb of years reporting the recall...	Comments
	NHTSA Recall Number	Canada DOT Recall Number	Prevost Recall #	Description	Manufacturer	Date notification to purchasers began	Date notification to purchasers was completed	From...	Through...	USA	Canada	Total	USA	Canada	Total	USA	Canada	Total				
1	12V-303	2012-191	SR12-16	ACCELERATOR PEDAL THROTTLE POSITION SENSOR REPLACEMENT (former wb10-33)	Prevost	2012-07-13	2012-07-13	2012-07-13	2013-09-30	258	144	402	251	143	394	97	99	98	0	0	1.2	Vehicles repaired under former warranty bulletin WB10-33 are included
2	12V-304	n/a	SR12-17	Tag Axle Hub Cap Screw Replacement	Prevost	n/a	n/a	2012-07-05	2013-09-30	2	n/a	2	2		2	100	n/a	100	0	0	1.3	
3	12V-300	2012-200	SR12-19	Steering Gearbox Bolts	Prevost	2012-08-02	2012-08-02	2012-08-02	2013-09-30	21	30	51	17	27	44	81	90	86	0	0	1.2	
4	12V-309	2012-203	SR12-20	Automatic Fire Detection and Suppression System (AFSS) – Rerouting Linear Thermal Detector (LTD)	Prevost	2012-07-18	2012-07-18	2012-07-18	2013-09-30	83	19	102	76	18	94	92	95	92	0	0	1.2	Vehicles repaired under former warranty bulletin WB09-16 are included
5	12V-315	2012-204	SR12-24	PROPER RUBBING PROTECTION FOR THE JUMP-STARTING POSITIVE TERMINAL BLOCK CABLE	Prevost	2012-07-17	2012-07-17	2012-07-17	2013-09-30	256	172	428	198	113	311	77	66	73	0	0	1.2	Vehicles repaired under former warranty bulletin WB10-04 are included
6	12V-325	n/a	SR12-25	Front Suspension Torqueing	Prevost	2012-07-06	2012-07-06	2012-07-06	2013-09-30	8	n/a	8	8		8	100	n/a	100	0	0	1.3	
7	12V-337	2012-221	SR12-26	Power Cable Protection	Prevost	2012-08-13	2012-08-13	2012-08-13	2013-09-30	211	80	291	134	69	203	64	86	70	0	0	1.1	
8	12V-435	n/a	SR12-29	AUTOMATIC FIRE DETECTION AND SUPPRESSION SYSTEM (AFSS) – PROTECTION OF LINEAR THERMAL DETECTOR (LTD)	Prevost	2012-09-27	2012-09-27	2012-09-27	2013-09-30	15	n/a	15	13		11	87	n/a	73	0	0	1.0	
9	12V-511	2012-348	SR12-39	Power Cable Rubbing	Prevost	2012-11-14	2012-11-14	2012-11-14	2013-09-30	51	40	91	43	33	76	84	83	84	0	0	0.9	
10	12V-564	2012-423	SR12-47	AFSS Cylinder Relocation	Prevost	2012-12-19	2012-12-19	2012-12-19	2013-09-30	79	10	89	75	10	85	95	100	96			0.8	
11	12v-205	n/a	SR12-57	Emergency Windows - wheel chair lift vehicles	Volvo Bus	2012-09-26	2012-09-26	2012-09-26	2013-09-30	27	n/a	27	17	n/a	17	63	n/a	63	0	0	1.0	
12	12V-295	n/a	SR12-59	Bodywork SW Update	Volvo Bus	2012-07-13	2012-07-13	2012-07-13	2013-09-30	9	n/a	9	9	n/a	9	100	n/a	100	0	0	1.2	
13	12V-313	n/a	SR12-61	PASSENGER SEAT TRACK INSPECTION AND REPAIR	Volvo Bus	2012-09-24	2012-09-24	2012-09-24	2013-09-30	145	n/a	145	104	n/a	104	72	n/a	72	0	0	1.0	
14	12V-450	n/a	SR12-65	Hose protection for hydraulic pressure pipe	Volvo Bus	2012-10-22	2012-10-22	2012-10-22	2013-09-30	246	n/a	246	193	n/a	193	78	n/a	78	0	0	1.0	
15	12V-539	n/a	SR12-69	WCL Safety Pins	Volvo Bus	2013-01-31	2013-02-05	2013-01-31	2013-09-30	53	n/a	53	32	n/a	32	60	n/a	60	0	0	0.7	
16	12V-600	2013-144	SR13-01	Radius Rod Support	Prevost	2013-01-28	2013-01-28	2013-01-28	2013-09-30	159	37	196	150	23	173	94	62	88	0	0	0.7	
17	13V-015	2013-014	SR13-03	AFSS Linear Thermal Detector Replacement	Prevost	2013-03-19 (epa us10)	2013-06-11 (epa us07)	2013-03-19	2013-09-30	438	69	507	298	38	336	68	55	66	0	0	0.5	
18	13V-021	2013-017	SR13-05	NEW SIDE MARKERS WITH NON-REFLECT.	Prevost	2013-02-05	2013-02-05	2013-02-05	2013-09-30	45	15	60	28	10	38	62	67	63	0	0	0.7	
19	13V-039	2013-059	SR13-07	ECU SOFT UPDATE L-H IDLE PARAMET	Prevost	2013-05-02	2013-05-02	2013-05-02	2013-09-30	1062	431	1493	670	289	959	63	67	64	0	0	0.4	
20	13V-055	2013-139	SR13-08	DRAGLINK TURNBUCKLE INSP. & REPL	Prevost	2013-05-02	2013-05-02	2013-05-02	2013-09-30	1442	472	1914	590	257	847	41	54	44	0	0	0.4	
21	13V-150	n/a	SR13-26	EMERGENCY EXIT SEQUENCE ON AWNING WINDOW DECALS	Prevost	2013-08-01 (Interim Letter)	2013-08-30	2013-08-30	2013-09-30	661	58	719	19	5	24	3	9		0	0	0.1	
22	13V-278	n/a	SR13-53	Tail Lamp Photometrics	Prevost	2013-08-22	2013-08-22	2013-08-22	2013-09-30	28	1	29	11	1	12	39	100	41	0	0	0.1	
23	13V-171	n/a	SR13-80	Mod. of Engine Speed Parameters for Limp Home Mode -Volvo D13 Engine ECU, SW Update	Volvo Bus	2013-07-02	2013-07-02	2013-07-02	2013-09-30	275	n/a	275	189	n/a	189	69	n/a	69	0	0	0.3	

Comment: Sr09-10 [nhtsa 9R-35], SR11-10 [11v-135] and sr11-52 [11v-364] removed as reported for more than 6 quarters;