

## Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.7

Report Date 2013-04-26  
Reporting Quarter Q1 2013

Date in (yyyy-mm-dd) format

Report Author Dominique Gagnon  
Phone 418-831-5432 x 235  
E-mail dominique.gagnon@volvo.com

NHTSA Recall Number	Prevost Recall #	Description	Manufacturer	Date notification to purchasers began	Date notification to purchasers was completed	Safety Recall Quarterly Report ...		Total Number of Vehicles/Pcs of Equipment Involved			Total Number Inspected & Remedied			Completion (%), per country			Total Number Inspected & NOT REQUIRING REMEDY	Vehicles determined to be Unreachable	For Internal use only: Nb of years reporting the recall...	Comments
						From...	Through...	USA	Canada	Total	USA	Canada	Total	USA	Canada	Total				
1	9E-35	SR09-10 INSP & REPL DRAG LINK TIE ROD END	n/a	2009-06-30	Renotification to customers on 2012-12-20	2009-06-30	2013-03-31	17	7	24	0	2	2	0	29	8	0	0	3.8	Recall applicable to parts sold in After-Market
2	11V-135	SR11-10 REPLACEMENT FUEL TANK SUPPORT	Prevost	2011-04-12	2011-04-12	2011-04-12	2013-03-31	39	10	49	35	10	45	90	100	92	0	0	2.0	
3	11V-364	SR11-52 FUSEBOX CONNECTIONS-INSPECT AND TORQUE TIGHTEN	Volvo Bus	2011-07-20	2011-07-20	2011-07-20	2013-03-31	179	n/a	179	160	0	160	89	n/a	89	0	0	1.7	
4	12V-303	SR12-16 ACCELERATOR PEDAL THROTTLE POSITION SENSOR REPLACEMENT (former wb10-33)	Prevost	2012-07-13	2012-07-13	2012-07-13	2013-03-31	260	142	402	252	141	393	97	99	98	0	0	0.7	Vehicles repaired under former warranty bulletin WB10-33 are included
5	12V-304	SR12-17 Tag Axle Hub Cap Screw Replacement	Prevost	n/a	n/a	2012-07-05	2013-03-31	2	n/a	2	2	2	2	100	n/a	100	0	0	0.7	
6	12V-300	SR12-19 Steering Gearbox Bolts	Prevost	2012-08-02	2012-08-02	2012-08-02	2013-03-31	21	30	51	14	24	38	67	80	75	0	0	0.7	
7	12V-309	SR12-20 Automatic Fire Detection and Suppression System (AFSS) - Rerouting Linear Thermal Detector (LTD)	Prevost	2012-07-18	2012-07-18	2012-07-18	2013-03-31	85	17	102	76	15	91	88	88	89	0	0	0.7	Vehicles repaired under former warranty bulletin WB09-16 are included
8	12V-315	SR12-24 PROPER RUBBING PROTECTION FOR THE JUMP-STARTING POSITIVE TERMINAL BLOCK CABLE	Prevost	2012-07-17	2012-07-17	2012-07-17	2013-03-31	256	172	428	196	99	297	77	56	69	0	0	0.7	Vehicles repaired under former warranty bulletin WB10-04 are included
9	12V-325	SR12-25 Front Suspension Torquing	Prevost	2012-07-06	2012-07-06	2012-07-06	2013-03-31	8	n/a	8	8	8	8	100	n/a	100	0	0	0.7	
10	12V-337	SR12-26 Power Cable Protection	Prevost	2012-08-13	2012-08-13	2012-08-13	2013-03-31	212	79	291	122	60	162	58	76	63	0	0	0.6	
11	12V-435	SR12-29 AUTOMATIC FIRE DETECTION AND SUPPRESSION SYSTEM (AFSS) - PROTECTION OF LINEAR THERMAL DETECTOR (LTD)	Prevost	2012-09-27	2012-09-27	2012-09-27	2013-03-31	15	n/a	15	7	7	7	47	n/a	47	0	0	0.5	
12	12V-511	SR12-39 Power Cable Rubbing	Prevost	2012-11-14	2012-11-14	2012-11-14	2013-03-31	52	39	91	31	27	58	60	69	64	0	0	0.4	
13	12V-564	SR12-47 AFSS Cylinder Relocation	Prevost	2012-12-19	2012-12-19	2012-12-19	2013-03-31	79	10	89	72	7	79	91	70	89	0	0	0.3	
14	12V-205	SR12-57 Emergency Windows - wheel chair lift vehicles	Volvo Bus	2012-09-26	2012-09-26	2012-09-26	2013-03-31	27	n/a	27	9	9	33	n/a	33	0	0	0.5		
15	12V-295	SR12-59 Bodywork SW Update	Volvo Bus	2012-07-13	2012-07-13	2012-07-13	2013-03-31	9	n/a	9	9	9	100	n/a	100	0	0	0.7		
16	12V-313	SR12-61 PASSENGER SEAT TRACK INSPECTION AND REPAIR	Volvo Bus	2012-09-24	2012-09-24	2012-09-24	2013-03-31	145	n/a	145	60	3	63	41	n/a	43	0	0	0.5	
17	12V-450	SR12-65 Hose protection for hydraulic pressure pipe	Volvo Bus	2012-10-22	2012-10-22	2012-10-22	2013-03-31	246	n/a	246	130	4	134	53	n/a	54	0	0	0.4	
18	12V-539	SR12-69 WCL Safety Pins	Volvo Bus	2013-01-31	2013-02-05	2013-01-31	2013-03-31	53	n/a	53	15	15	28	n/a	28	0	0	0.2		
19	12V-600	SR13-01 Radius Rod Support	Prevost	2013-01-28	2013-01-28	2013-01-28	2013-03-31	158	37	195	44	15	59	28	41	30	0	0	0.2	
20	13V-015	SR13-03 AFSS Linear Thermal Detector Replacement	Prevost	2013-03-19	2013-03-22	2013-03-19	2013-03-31	440	67	507	161	9	170	37	13	34	0	0	0.0	Total qty mentioned here is for us10 engine vehicles only, interim notice sent out to owners of us07 vehicles involved on 2013-03-19. Total qty of vehicles involved will be adjusted at next quarterly report to include owners of us07 engine.
21	13V-021	SR13-05 NEW SIDE MARKERS WITH NON-REFLEC	Prevost	2013-02-05	2013-02-05	2013-02-05	2013-03-31	44	16	60	8	5	13	18	31	22	0	0	0.2	