

# IMPORTANT SAFETY RECALL

This notice applies to your vehicle



565 de la Montagne Street  
Valcourt, Québec, Canada J0E 2L0  
T 450.532.2211 F 450.532.5133

[www.brp.com](http://www.brp.com)

February 26, 2015

## Re: Can-Am® Spyder® roadster - Fuel Cap Replacement – Re-Notification

Dear Can-Am roadster Owner,

BRP is sending you this re-notification letter because our records show that you own a potentially affected vehicle that needs to have its fuel cap inspected and replaced if needed.

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act, the U.S. Environmental Protection Agency (EPA) and, the California Air Resources Board (CARB).

BRP has decided that a defect which relates to motor vehicle safety exists on certain Can-Am roadster models and launched a safety recall in December 2012.

### What is the potential problem?


The fuel cap may not seal properly the fuel tank filler neck. Fuel vapors in the presence of an ignition source could result in a fire.

### What should you do?

For reference, please see below pictures that will help you identify that the fuel cap on your vehicle is the improved version. The improved fuel cap has a reddish color seal and a different size handle. If your vehicle is equipped with the improved version, no further action is needed.



NEW IMPROVED FUEL CAP – REDDISH SEAL



NEW IMPROVED FUEL CAP – EXTERIOR SHAPE

Ski-Doo  
Lynx  
Sea-Doo  
Evinrude  
Rotax  
Can-Am

**If you suspect that it is not the improved version, or if you are unsure:**

Make an appointment to have your fuel cap inspected and replaced if needed. The replacement should take less than 10 minutes to complete. The dealer will perform this work at no charge to you.

If you had this repair done before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

**What to do if you feel this notice is an error?**

This notice was mailed to you according to the most current information we have available. If you no longer own this vehicle or some information in this notice is incorrect, please contact BRP at your earliest convenience.

If you believe that the dealer or BRP has failed or is unable to remedy the defect within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E. Washington, D.C. 20590, or call the toll free Auto Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>. If you are a vehicle lessor, federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

**If you have questions, need assistance, or to find the nearest authorized BRP Can-Am roadster dealer:**

- Visit [www.can-am.brp.com](http://www.can-am.brp.com)
- Or call: 1-888-272-9222  
9:00 AM to 9:00 PM Eastern time Monday to Friday

Your continued satisfaction with your roadster is important to us. Please understand that we have taken this action in the interest of your safety and your vehicle's proper operation. We apologize for any inconvenience this may cause you.

Thank you for your immediate attention to this matter.

Sincerely,  
After-Sales Service Department