

13V-014
(6 pages)**DEFECT INFORMATION REPORT**

Southeast Toyota Distributors, LLC (SET) submits the following Defect Information Report pursuant to 49 CFR Part 573.6(a):

Vehicle Distributor Name:

Southeast Toyota Distributors, LLC
100 Jim Moran Blvd
Deerfield Beach, Florida 33442
(954) 429-2000

1. Identification of Affected Vehicles:

SET has determined that potentially affected vehicles fall within the VIN range set forth in **Attachment "A,"** attached hereto.

2. Total Number of Vehicles Potentially Affected:

SET will recall 3,235 vehicles.

3. Percentage of Vehicles Estimated to Actually Experience Defect:

SET estimates that each of the subject vehicles may not have had a calibration check in accordance with Toyota's standard post-repair procedure after the installation of certain accessories. SET estimates that few, if any, of the vehicles will require recalibration.

4. Description of Defect:

SET has determined that the standard sensor calibration test may not have been conducted on certain vehicles after installation of leather seat covers, seat heaters, or headrest DVD entertainment devices. If the sensors are not properly calibrated, the occupant sensing system may not operate as designed. Airbag deployment or non-deployment could result in injury in the event of a crash.

5. Chronology of Principal Events:

SET routinely follows a post-repair procedure published by Toyota to check the calibration of the occupant sensors in the front passenger seat when installing certain accessories in the front passenger seat. In early to mid November 2012, SET discovered that a technician was not using the post-repair diagnostic analyzer to check the calibration of the sensors as required. Over the course of the following weeks, SET investigated the scope and found that it was limited to two technicians. SET also conducted a calibration sensitivity study. Based on that study, SET determined that there is a potential that recalibration based on the post-repair procedure may be required. SET identified each of the vehicles worked on by the particular technicians at issue and those vehicles form the population for this recall.

8. Description of Corrective Repair Action:

SET will conduct a sensitivity check of the front passenger seat Occupant Detection Sensors and recalibrate the system to meet Toyota specifications if necessary. All affected vehicles are under warranty and SET anticipates no reimbursement claims.

9. Recall Schedule:

Dealer and Owner notification letters will be provided to NHTSA as they are issued. SET anticipates beginning dealer and customer notification in January, 2013.

ATTACHMENT A

Southeast Toyota Distributors, LLC
Identification of Affected Vehicles VIN Range Attachment
Airbag Sensor Calibration

Series	WMI	MY	VDS	From	To
Tacoma 4x2	3TM	2009	JU62N	M090916	M091244
		2010	JU4GN KU4HM	M104228 M023774	M100235 M025736
		2011	JU4GN KU4HN	M113836 M029941	M111558 M029629
		2012	JU4GN	M137345	M138055
	5TE	2010	JU4GN KU4HN	Z713754 Z715603	Z688669 Z701523
		2011	JU4GN JX4GN KU4HN	X001032 X004813 X001334	X005945 X002216 X001565
			JU4GN JX4GN KU4HN	X022657 X009733 X002056	X027686 X011123 X002056
	5TF	2009	LU42N	M036543	M036543
		2010	LU4EN MU4FN	M039473 M020586	M049539 M022929
		2011	LU4EN MU4FN	M077756 M036790	M074165 M034946
		2012	LU4EN MU4FN	M081623 M040724	M101593 M040448
Tacoma 4X4	3TM	2010	LU4EN	Z708487	Z694095
		2010	MU4FN	Z694041	Z676781
	5TF	2011	LU4EN MU4FN	X015038 X002880	X008078 X002880
		2012	LU4EN MU4FN	X031119 X008238	X047163 X004939
	JTE	2009	BU14R ZU14R ZU17R	K040834 K025773 K025976	K040834 K025834 K025976
		2010	BU5JR ZU5JR	5008588 5007892	5027852 5013084
		2011	BU5JR ZU5JR	5035100 5014357	5072185 5032719
		2012	BU5JR ZU5JR	5108642 5044095	5077393 5039073

AVALON	4T1	2009	BK36B	U346301	U346301
		2010	BK3DB	U358866	U361362
CAMRY	4T1	2009	BE46K	U907701	U912612
		2010	BF3EK	U003523	U603008
			BK3EK	U117387	U776498
		2012	BF1FK	U003219	U598967
	4T4		BK1FK	U008720	U519003
		2010	BF3EK	R006489	R074363
		2011	BF3EK	R185392	R195492
		2012	BF1FK	R189012	R182648
CAMRY HYBRID	JTN	2010	BF3EK	3000770	3001901
	4T1	2009	BB46K	U109659	U105527
		2010	BB3EK	U113590	U125907
		2011	BB3EK	U140278	U141924
		2012	BD1FK	U004442	U051560
COROLLA	1NX	2010	BU4EE	Z277164	Z362982
	2T1	2010	BU4EE	C390713	C504586
		2011	BU4EE	C602253	C746702
		2012	BU4EE	C899916	C772519
	5YF	2013	BU4EE	C949198	C949198
		2012	BU4EE	P027917	P063987
	JTD	2013	BU4EE	P081761	P081761
		2010	BU4EE	J078861	J082453
		2011	BU4EE	9123899	9137064
FJ CRUISER	JTE	2009	BU11F	K069431	K069431
		2010	BU4BF	K072860	K097763
			ZU4BF	K010024	K010024

HIGHLANDER	STD	2010	BK3EH	S034507	S036635
			KK3EH	S020366	S020366
		2011	XK3EH	S004638	S004875
		2011	YK3EH	S005755	S005755
		2011	ZA3EH	S001961	S007217
	JTE	2012	ZK3EH	S001746	S020661
		2012	BK3EH	S066051	S076148
		2012	DK3EH	S079420	S092257
		2012	YK3EH	S046232	S044799
		2012	ZA3EH	S009091	S016078
		2013	ZK3EH	S034585	S046128
		2009	DK3EH	S116313	S116313
		2009	YK3EH	S080947	S082267
		2009	ZA3EH	S017581	S029910
		2009	ZK3EH	S051601	S084864
		2010	ZK3EH	S092171	S092171
HIGHLANDER HYBRID	JTE	2009	DA41A	2005792	2005846
HIGHLANDER HYBRID	JTE	2010	DS41A	2088247	2085386
PRIUS	JTD	2009	DS42A	2090727	2087329
PRIUS		2010	DS43A	2071549	2087903
PRIUS		2011	ES41A	2146591	2146844
PRIUS		2012	ES43A	2146840	2146840
PRIUS V	JTD	2009	DK3EH	2164100	2155059
PRIUS V	JTD	2010	XK3EH	2096206	2096206
PRIUS V	JTD	2011	YK3EH	2097050	2100691
PRIUS V	JTD	2012	ZA3EH	2009554	2008967
PRIUS V	JTD	2012	ZK3EH	2102563	2106412
		2009	EW41A	2037187	2037187
		2010	JW3EH	2040125	2037890
		2012	ZN3EU	3039656	3039656
		2009	ZF33V	W012660	W015368

RAV4	2T3	2010	BF4DV	W078421	W078421
			KF4DV	W034868	W049570
			WF4DV	W029395	W026955
			ZF4DV	W027885	W047309
			ZK4DV	W005081	W005264
		2011	BF4DV	W144196	W097768
			DK4DV	W053611	W053611
			JF4DV	W143820	W143820
			KF4DV	W062820	W059776
	JTM	2012	RK4DV	W049533	W049533
			WF4DV	W063071	W095551
			WK4DV	W011233	W011233
			YF4DV	W064565	W092729
			ZF4DV	W052696	W090050
			ZK4DV	W010362	W009902
			BF4DV	W233217	W233217
			KF4DV	W107532	W106594
			ZF4DV	W107262	W144061
SEQUOIA	5TD	2009	BK32V	5082041	5082041
			ZF33V	5010935	D015476
			ZF35V	5010371	5010371
		2010	BK4DV	D012893	D012893
			KF4DV	5019344	5020618
			KK4DV	5026847	5026847
			RF4DV	5033832	5022356
			WF4DV	5024048	5027796
			ZF4DV	5023060	D027168
		2011	RF4DV	5042461	5047922
			RK4DV	5104999	5104999
			WF4DV	5033939	5036886
			ZF4DV	5033492	D030864
SIENNA	5TD	2010	BW5G1	S026135	S024735
			JW5G1	S035305	S035305
			ZY5G1	S029551	S024414
		2011	BW5G1	S050859	S049799
			BY5G1	S052690	S052690
			ZY5G1	S032877	S036726
		2012	KY5G1	S038476	S038476
			ZY5G1	S039393	S042552
		2010	KK4CC	S337007	S336244
		2011	DK3DC	S021362	S021362
			KA3DC	S006989	S002369
			KK3DC	S010407	S120199
			XK3DC	S121524	S088356
			YK3DC	S125771	S127177
			ZK3DC	S130366	S176057
		2012	KA3DC	S012887	S011127
			KK3DC	S191073	S229117
			YK3DC	S228166	S179014
		2013	YK3DC	S279929	S279929

TUNDRA 4X2	5TF		2010	EY5F1	X082221	X095400
				FY5F1	X092368	X092368
				RM5F1	X010402	X016868
				RU5F1	X023537	X023660
TUNDRA 4X4	5TF			RY5F1	X082219	X094233
			2011	EY5F1	X107197	X103982
				FY5F1	X100111	X105778
				RM5F1	X026688	X032375
VENZA	4T3			RY5F1	X115298	X114529
			2012	EY5F1	X119013	X132285
				RM5F1	X038238	X036315
				RY5F1	X123296	X128737
			2013	RM5F1	X051859	X051859
				CW5F1	X009952	X009952
			2010	DW5F1	X133461	X102757
				UM5F1	X014906	X156262
				CW5F1	X011578	X011578
			2011	DW5F1	X193788	X207390
				HW5F1	X207909	X158819
				UW5F1	X178806	X204599
				DW5F1	X215726	X263850
			2012	HW5F1	X248967	X248967
				UM5F1	X030997	X030699
				UW5F1	X214349	X211019
			2013	HW5F1	X272850	X272850
				BE11A	U007573	U005822
			2009	BK11A	U015137	U021907
				ZE11A	U013080	U020013
				ZK11A	U013192	U017153
				BA3BB	U010012	U010012
			2010	BK3BB	U035843	U043778
				ZA3BB	U034201	U035159
				ZK3BB	U024645	U031321
				BA3BB	U019663	U028469
			2011	BK3BB	U059351	U057208
				ZA3BB	U039349	U053601
				ZK3BB	U034973	U045981
				BK3BB	U068866	U068866
			2012	ZA3BB	U063040	U061357
				ZK3BB	U052214	U052272
				ZA3BB	U066131	U066131
			2013	ZK3BB	U054031	U054031