OMB Control No.: 2127-0004

# **Part 573 Safety Recall Report**

# 13V-130

**Manufacturer Name :** Mazda North American Operations

**Submission Date :** DEC 22, 2015 **NHTSA Recall No. :** 13V-130 **Manufacturer Recall No. :** 6913D



#### **Manufacturer Information:**

Manufacturer Name: Mazda North American Operations

Address: 1025 Connecticut Avenue, NW

Suite 910 Washington DC 20036

Company phone: 800-222-5500

### **Population:**

Number of potentially involved: 149 Estimated percentage with defect: 100

#### **Vehicle Information:**

Vehicle: 2004-2004 MAZDA MAZDA6

Vehicle Type: LIGHT VEHICLES

Body Style:

Power Train: NR

Descriptive Information: 2004 model year Mazda6, built from January 14, 2003 through May 29, 2003 at

Auto Alliance International, U.S.

Production Dates: JAN 14, 2003 - MAY 29, 2003

#### **VIN (Vehicle Identification Number) Range**

 $\begin: NR \\ \begin : NR \\ \begin : NR \\ \begin : NR$ 

Vehicle: 2003-2003 MAZDA MAZDA6

Vehicle Type: LIGHT VEHICLES

Body Style : NR Power Train : NR

**Descriptive Information: NR** 

Production Dates: JAN 14, 2003 - MAY 29, 2003

#### **VIN (Vehicle Identification Number) Range**

Begin: NR End: NR Not sequential VINs

Vehicle: 2004-2004 MAZDA RX-8 Vehicle Type: LIGHT VEHICLES

Body Style : NR Power Train : NR

**Descriptive Information: NR** 

Production Dates: JUN 25, 2003 - JUN 30, 2003

VIN (Vehicle Identification Nu	mber) Range	
Begin : NR	End : NR	☐ Not sequential VINs

### **Description of Defect:**

Description of the Defect: Updated on Dec.22, 2015; The subject 149 vehices under 13V130, 2003-2004MY

Mazda6, 147units, and 2004 MY RX-8, 2units ,are moved into new Part573 submitted on 12/22/2015 involved with 2003-2008MY Mazda6, 2005-2007MY Mazdaspeed6 and 2004MY RX-8. Therefore, Mazda is closing this 13V130. Mazda is recalling certain model year 2003-2004 Mazda6 vehicles manufactured January 14, 2003, through May 29, 2003; and 2004 RX-8 vehicles manufactured June 25, 2003, through June 30, 2003, to address a safety defect in the passenger side air bag which may produce excessive internal pressure causing the inflator to rupture upon deployment of the air bag.

FMVSS 1 :NR FMVSS 2 :NR

Description of the Safety Risk: In the event of a crash necessitating deployment of the passenger's air bag, the

inflator could rupture with metal fragments striking and potentially seriously

injuring the passenger seat occupant or other occupants.

Description of the Cause: NR

Identification of Any Warning that can Occur: NR

**Component Manufacturer** 

Name: Takata Corporation

Address : NR

NR

Country: NR

# **Chronology:**

NR

#### **Description of Remedy:**

Description of Remedy Program: Owners of all vehicles on which a defective air bag may have been installed

as original equipment will be notified. Dealers will inspect vehicles, and where a defective air bag inflator is identified, the inflator will be replaced, free of charge. The safety recall began on June 3, 2013. Owners may contact Mazda Customer Assistance Center at 1-800-222-5500, option #6. Mazda's

recall campaign number is 6913D.

How Remedy Component Differs from Recalled Component: NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule:** 

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date: MAY 31, 2013 - NR

\* NR - Not Reported