

**Part 573 Safety Recall Report****13V-354****Manufacturer Name :** Hyundai Motor America**Submission Date :** NOV 10,2014**NHTSA Recall No. :** 13V-354**Manufacturer Recall No. :** 113**Manufacturer Information :**

Manufacturer Name : Hyundai Motor America

Address : 10550 TALBERT AVENUE  
FOUNTAIN VALLEY CA 92708

Company phone : 1-714-965-3920

**Population :**

Number of potentially involved : 364,502

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2011-2011 HYUNDAI AZERA

Vehicle Type : LIGHT VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Model year 2006 through 2010 Hyundai Sonata vehicles produced beginning on March 1, 2005 through January 21, 2010 and model year 2006 through 2011 Hyundai Azera vehicles produced beginning on September 27, 2005 through November 22, 2010 that are registered in and operated in the following 20 "salt belt" states and the District of Columbia.

Production Dates : SEP 27, 2020 - NOV 22, 2010

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2010-2010 HYUNDAI AZERA

Vehicle Type : LIGHT VEHICLES

Body Style : NR

Power Train : NR

Descriptive Information : NR

Production Dates : SEP 27, 2005 - NOV 22, 2010

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2009-2009 HYUNDAI AZERA

Vehicle Type : LIGHT VEHICLES

Body Style : NR

Power Train : NR





**Description of Defect :**

Description of the Defect : Hyundai is recalling certain model year 2006-2010 Sonata vehicles manufactured March 1, 2005, through January 21, 2010; and model year 2006-2011 Azera vehicles manufactured September 27, 2005, through November 22, 2010 originally sold in, or currently registered in, Connecticut, Delaware, Illinois, Indiana, Iowa, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, West Virginia, Wisconsin and the District of Columbia. Road salt and water can enter portions of the rear crossmember, leading to corrosion of the crossmember steel. This may lead to detachment of one of the rear control arms.

Description of the Safety Risk : Control arm separation may suddenly change the rear wheel alignment, affecting the handling of the vehicle, increasing the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Hwa Sin America Corp

Address : NR

NR

Country : United States

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : Hyundai will notify owners, and dealers will repair or replace the crossmember assembly. The recall began on October 8, 2013. Owners may contact Hyundai Customer Care Center at 1-800-633-5151. Hyundai's recall number is 113.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : AUG 30, 2013 - NR

\* NR - Not Reported