

GM CUSTOMER CARE AND AFTERSALES  
DCS2993  
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 27, 2013

Subject: 12180C – Safety Recall  
Driver Door Switch Short Circuit  
Revised Service Procedure

Models: 2006 Chevrolet TrailBlazer EXT, GMC Envoy XL; 2006-07 Buick  
Rainier, Chevrolet TrailBlazer, GMC Envoy

To: All Buick, Chevrolet, and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, Used Vehicle Sales Manager,  
and Warranty Administrator

Bulletin 12180C has been revised to include an inspection and service procedure  
overview in the service procedure. Please discard all copies of bulletin 12180B.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES