



Mitsubishi Motors North America, Inc.

PARTS BULLETIN

SUBJECT:

**2013 OUTLANDER SPORT LEFT FRONT STRUT
-SAFETY RECALL CAMPAIGN-**

No: 33-US-01-13

Date: JULY 2013

Model:
2013 Outlander Sport

Purpose:

Due to a part manufacturing error, the left front strut assembly on certain 2013 Outlander Sport vehicles may have an improperly welded stabilizer link bracket. On affected parts, the bracket may become disconnected from the strut assembly. If use continues under this condition, a detached bracket could cause damage to the tire and/or brake hose.

Safety Recall Bulletin (SR-13-008) has been created to instruct dealers to inspect the left front strut, and replace if necessary.

AFFECTED VEHICLE:

Certain 2013 Outlander Sport vehicles built from January 17, 2013 – January 25, 2013

PARTS INFORMATION

Use the genuine Mitsubishi Parts listed below:

PART NUMBER	QUANTITY	PNC	DESCRIPTION
4060A473	1	40041L	STRUT,FR SUSP,LH
MU431503	1	41990C	NUT,LOCKING,M12

- Part replacement required only for inspected vehicles with a left front strut that is stamped with a date code of “3A10”
- If a replacement is required a new locking nut must be used with the new strut.
- There will be no forced allocation or parts.
- There will be no need to stock up on the parts.

Contact your local Zone Representative, District Parts and Service manager, or Facing PDC for questions.

