



Safety Recall: 2007–08 Odyssey VSA System Unexpectedly Activates

BACKGROUND

Because of a combination of installed VSA system components and software, it is possible for the VSA system to unexpectedly apply the brakes without turning on the brake lights, increasing the risk of a crash. Each time the vehicle is started, the VSA system calibrates the yaw rate sensor. If the vehicle is driven in a specific manner, the VSA system may not properly complete the calibration.

Owners of affected vehicles will receive a notification and instructions about how to properly calibrate the VSA system before driving to prevent unintended braking. These instructions are available at www.recalls.honda.com.

Later, when parts become available, customers will be sent another notification about repairing their vehicle.