

## IMPORTANT SAFETY RECALL NOTICE

Dear Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Oreion Manufacturing LLC has decided certain model year 2011-2013 Reeper Low Speed Vehicles fail to conform to the requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 500, "Low Speed Vehicles." The affected vehicles may exceed the maximum permitted speed of 25 mph. Also, the vehicles are not equipped with red reflectors on the rear of the vehicle and the Gross Vehicle Weight Rating (GVWR) of these vehicles are incorrectly listed on the certification label which is a violation of Part 567, "Certification."

- a) Your Reeper Low Speed Vehicle is being recalled.
- b) Contact your dealer to arrange for installation of a shift plate and throttle limiter that will bring your Low Speed Vehicle in to compliance with Federal Motor Vehicle Safety Standard (FMVSS)571.500. This remedy will be provided and installed by your local dealer at no cost to you.
- c) Please place the enclosed Part 567 Certification Label over your current Certification Label. The enclosed diagram shows where to find and cover your Certification Label. (Please refer to IMAGE 3)
- d) Please place the enclosed reflective tape on both rear sides of your Reeper Low Speed Vehicle. See enclosed diagram for exact location. (Please refer to IMAGE 1 AND 2)

Why is a recall being conducted? The Reeper Low Speed Vehicle does not comply with several requirements of the Federal Motor Vehicle Safety Standard (FMVSS)571.500 Low Speed Vehicles. When tested by The National Highway Traffic Safety Administration (NHTSA) during July of 2013 the speed obtained by the testing contractor exceeded the maximum speed allowed for Low Speed Vehicles of 25 mph. Oreion has never intended for the Reeper to be anything other than a Low Speed Vehicle and the consequences of the Reeper being able to be driven at speeds higher than allowed are severe and include possible injury to occupants.

What are we doing about the problem? Shift limiter plates and throttle limiters are being distributed to dealers. There will be no charge for the installation of the plate. Enclosed with this letter is a new Certification label with accurate GVWR and GVAW information. Enclosed as well as a reflective tape that will remedy the visibility issue.

What should you do? Please contact your local dealer at your earliest convenience to have the shift limiter plate installed. The other noncompliance issues can be addressed and remedied by the owner by placing the enclosed Certification label and the reflective tape on your Reeper in the location identified by the enclosed diagram.

What should you do if you no longer own the Reeper? Please forward the new owner information to Oreion.

Who should you contact if you have further questions or concerns? Please contact Oreion Motors LLC at (505)-916-1206 or [info@oreionmotors.com](mailto:info@oreionmotors.com).

If after having attempted to take advantages of this recall you believe that you have not been able to have your Reeper remedied without charge and within a reasonable amount of time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E, Washington, D.C. 20590 or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153): or go to <http://www.safercar.gov>.

Federal law requires any lessor who receives a notification of a determination of a safety-related defect or noncompliance pertaining to any leased motor vehicle shall send the notice to the lessee within 10 days.

We apologize for any inconvenience this safety recall may cause, but your safety is our first concern.

Sincerely,



Oreion Motors LLC