

DAIMLER

Daimler Trucks North America
Nasser Zamani
Senior Manager
Compliance and Regulatory Affairs

May 5, 2014

Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attention: Recall Management Division (NVS-215, Rm. W45-206)
1200 New Jersey Avenue S.E.
Washington D.C. 20590

**Re: Defect Information Report – Supplemental Report No. 3
13V-605, FL-655, Sterling Bullet Left Tie Rod Ends
2nd Interim Owner Notice**

Ms. Lewis,

In accordance with Part 573 of Title 49 of the Code of Federal Regulations, Daimler Trucks North America LLC herewith submits supplemental defect information and a representative copy of the document distributed to owners.

(c)(8)(ii) Owners of 2601, vehicles were notified on April 28, 2014.

(c)(10) A copy of communications sent to owners is attached.

Please contact me if you have any questions.

Sincerely yours,



Nasser Zamani

Cc: Amy Martin, CAL-OSHA
Attachment

A Daimler Company

Daimler Trucks North America LLC
4747 N. Channel Avenue
Portland OR 97217-7699
503-745-6910 Phone
503-745-5544 Fax
Nasser.Zamani@Daimler.com

Daimler Trucks North America LLC

Daimler Trucks North America LLC
P.O. Box 4090
Portland, OR 97208-4090
800.547.0712 Phone
503.745.9009 Fax

April 2014
FL655
Second Interim Recall Notice
NHTSA #13V-605

IMPORTANT SAFETY RECALL

Subject: Sterling Bullet Left Tie Rod Ends

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daimler Trucks North America LLC (DTNA), on behalf of Chrysler Group LLC, has decided that a defect which relates to motor vehicle safety exists on specific Sterling Bullet vehicles manufactured October 15, 2007, through November 10, 2008.

Certain vehicles may experience a fracture of the left tie rod ball stud resulting in the potential loss of directional stability.

This letter is to provide important information regarding an interim remedy. DTNA is currently validating the final repair and securing replacement parts. Before the final remedy is available, DTNA recommends the left tie rod end be inspected by an authorized Daimler Trucks North America dealer. Please contact a DTNA dealer to schedule the interim remedy for your vehicle. If the left tie rod is misaligned, a new tie rod end will be installed. If the left tie rod is aligned properly, no further action is needed until the final remedy is available.

You will be notified by mail when the final remedy is available. **All vehicles will require the final remedy, including those that have an interim tie rod end replacement.**

If you do not own the vehicle that corresponds to the identification number(s), which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner.

If you have questions about this Recall, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time Monday through Friday, e-mail address DTNA.Warranty.Campaigns@Daimler.com, or the Customer Assistance Center at (800) FTL-HELP after normal business hours. If you are not able to have the defect remedied without charge and within a reasonable time, you may wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Vehicle Safety Hotline at (888) 327-4236 (TTY: 800-424-9153); or to <http://www.safercar.gov>.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT
Enclosure