

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.7

Report Date 2013-10-29, revised January 31 2014  
Reporting Quarter Q3 2013

Date in (yyyy-mm-dd) format

Report Author Dominique Gagnon  
Phone 418-831-5432 x 235  
E-mail dominique.gagnon@volvo.com

|    |                     |                          |                  |                                                                                                      |              |                                       |                                               | Safety Recall Quarterly Report ... |            | Total Number of Vehicles/Pces of Equipment Involved |        |       | Total Number Inspected & Remedied |        |       | Completion (%), per country |        |       | Total Number Inspected & NOT REQUIRING REMEDY | Vehicles determined to be Unreachable | For internal use only: Nb of years reporting the recall... | Comments                                                              |
|----|---------------------|--------------------------|------------------|------------------------------------------------------------------------------------------------------|--------------|---------------------------------------|-----------------------------------------------|------------------------------------|------------|-----------------------------------------------------|--------|-------|-----------------------------------|--------|-------|-----------------------------|--------|-------|-----------------------------------------------|---------------------------------------|------------------------------------------------------------|-----------------------------------------------------------------------|
|    | NHTSA Recall Number | Canada DOT Recall Number | Prevost Recall # | Description                                                                                          | Manufacturer | Date notification to purchasers began | Date notification to purchasers was completed | From...                            | Through... | USA                                                 | Canada | Total | USA                               | Canada | Total | USA                         | Canada | Total |                                               |                                       |                                                            |                                                                       |
| 1  | 12V-303             | 2012-191                 | SR12-16          | ACCELERATOR PEDAL THROTTLE POSITION SENSOR REPLACEMENT (former wb10-33)                              | Prevost      | 2012-07-13                            | 2012-07-13                                    | 2012-07-13                         | 2013-09-30 | 258                                                 | 144    | 402   | 251                               | 143    | 394   | 97                          | 99     | 98    | 0                                             | 0                                     | 1.2                                                        | Vehicles repaired under former warranty bulletin WB10-33 are included |
| 2  | 12V-304             | n/a                      | SR12-17          | Tag Axle Hub Cap Screw Replacement                                                                   | Prevost      | n/a                                   | n/a                                           | 2012-07-05                         | 2013-09-30 | 2                                                   | n/a    | 2     | 2                                 |        | 2     | 100                         | n/a    | 100   | 0                                             | 0                                     | 1.3                                                        |                                                                       |
| 3  | 12V-300             | 2012-200                 | SR12-19          | Steering Gearbox Bolts                                                                               | Prevost      | 2012-08-02                            | 2012-08-02                                    | 2012-08-02                         | 2013-09-30 | 21                                                  | 30     | 51    | 17                                | 27     | 44    | 81                          | 90     | 86    | 0                                             | 0                                     | 1.2                                                        |                                                                       |
| 4  | 12V-309             | 2012-203                 | SR12-20          | Automatic Fire Detection and Suppression System (AFSS) – Rerouting Linear Thermal Detector (LTD)     | Prevost      | 2012-07-18                            | 2012-07-18                                    | 2012-07-18                         | 2013-09-30 | 83                                                  | 19     | 102   | 76                                | 18     | 94    | 92                          | 95     | 92    | 0                                             | 0                                     | 1.2                                                        | Vehicles repaired under former warranty bulletin WB09-16 are included |
| 5  | 12V-315             | 2012-204                 | SR12-24          | PROPER RUBBING PROTECTION FOR THE JUMP-STARTING POSITIVE TERMINAL BLOCK CABLE                        | Prevost      | 2012-07-17                            | 2012-07-17                                    | 2012-07-17                         | 2013-09-30 | 256                                                 | 172    | 428   | 198                               | 113    | 311   | 77                          | 66     | 73    | 0                                             | 0                                     | 1.2                                                        | Vehicles repaired under former warranty bulletin WB10-04 are included |
| 6  | 12V-325             | n/a                      | SR12-25          | Front Suspension Torqueing                                                                           | Prevost      | 2012-07-06                            | 2012-07-06                                    | 2012-07-06                         | 2013-09-30 | 8                                                   | n/a    | 8     | 8                                 |        | 8     | 100                         | n/a    | 100   | 0                                             | 0                                     | 1.3                                                        |                                                                       |
| 7  | 12V-337             | 2012-221                 | SR12-26          | Power Cable Protection                                                                               | Prevost      | 2012-08-13                            | 2012-08-13                                    | 2012-08-13                         | 2013-09-30 | 211                                                 | 80     | 291   | 134                               | 69     | 203   | 64                          | 86     | 70    | 0                                             | 0                                     | 1.1                                                        |                                                                       |
| 8  | 12V-435             | n/a                      | SR12-29          | AUTOMATIC FIRE DETECTION AND SUPPRESSION SYSTEM (AFSS) – PROTECTION OF LINEAR THERMAL DETECTOR (LTD) | Prevost      | 2012-09-27                            | 2012-09-27                                    | 2012-09-27                         | 2013-09-30 | 15                                                  | n/a    | 15    | 13                                |        | 11    | 87                          | n/a    | 73    | 0                                             | 0                                     | 1.0                                                        |                                                                       |
| 9  | 12V-511             | 2012-348                 | SR12-39          | Power Cable Rubbing                                                                                  | Prevost      | 2012-11-14                            | 2012-11-14                                    | 2012-11-14                         | 2013-09-30 | 51                                                  | 40     | 91    | 43                                | 33     | 76    | 84                          | 83     | 84    | 0                                             | 0                                     | 0.9                                                        |                                                                       |
| 10 | 12V-564             | 2012-423                 | SR12-47          | AFSS Cylinder Relocation                                                                             | Prevost      | 2012-12-19                            | 2012-12-19                                    | 2012-12-19                         | 2013-09-30 | 79                                                  | 10     | 89    | 75                                | 10     | 85    | 95                          | 100    | 96    |                                               |                                       | 0.8                                                        |                                                                       |
| 11 | 12v-205             | n/a                      | SR12-57          | Emergency Windows - wheel chair lift vehicles                                                        | Volvo Bus    | 2012-09-26                            | 2012-09-26                                    | 2012-09-26                         | 2013-09-30 | 27                                                  | n/a    | 27    | 17                                | n/a    | 17    | 63                          | n/a    | 63    | 0                                             | 0                                     | 1.0                                                        |                                                                       |
| 12 | 12V-295             | n/a                      | SR12-59          | Bodywork SW Update                                                                                   | Volvo Bus    | 2012-07-13                            | 2012-07-13                                    | 2012-07-13                         | 2013-09-30 | 9                                                   | n/a    | 9     | 9                                 | n/a    | 9     | 100                         | n/a    | 100   | 0                                             | 0                                     | 1.2                                                        |                                                                       |
| 13 | 12V-313             | n/a                      | SR12-61          | PASSENGER SEAT TRACK INSPECTION AND REPAIR                                                           | Volvo Bus    | 2012-09-24                            | 2012-09-24                                    | 2012-09-24                         | 2013-09-30 | 145                                                 | n/a    | 145   | 104                               | n/a    | 104   | 72                          | n/a    | 72    | 0                                             | 0                                     | 1.0                                                        |                                                                       |
| 14 | 12V-450             | n/a                      | SR12-65          | Hose protection for hydraulic pressure pipe                                                          | Volvo Bus    | 2012-10-22                            | 2012-10-22                                    | 2012-10-22                         | 2013-09-30 | 246                                                 | n/a    | 246   | 193                               | n/a    | 193   | 78                          | n/a    | 78    | 0                                             | 0                                     | 1.0                                                        |                                                                       |
| 15 | 12V-539             | n/a                      | SR12-69          | WCL Safety Pins                                                                                      | Volvo Bus    | 2013-01-31                            | 2013-02-05                                    | 2013-01-31                         | 2013-09-30 | 53                                                  | n/a    | 53    | 32                                | n/a    | 32    | 60                          | n/a    | 60    | 0                                             | 0                                     | 0.7                                                        |                                                                       |
| 16 | 12V-600             | 2013-144                 | SR13-01          | Radius Rod Support                                                                                   | Prevost      | 2013-01-28                            | 2013-01-28                                    | 2013-01-28                         | 2013-09-30 | 159                                                 | 37     | 196   | 150                               | 23     | 173   | 94                          | 62     | 88    | 0                                             | 0                                     | 0.7                                                        |                                                                       |

|    |                     |                          |                  |                                                                                     |              |                                       |                                               | Safety Recall Quarterly Report ... |            | Total Number of Vehicles/Pces of Equipment Involved |        |       | Total Number Inspected & Remedied |        |       | Completion (%), per country |        |       | Total Number Inspected & NOT REQUIRING REMEDY | Vehicles determined to be Unreachable | For internal use only: Nb of years reporting the recall... | Comments                        |
|----|---------------------|--------------------------|------------------|-------------------------------------------------------------------------------------|--------------|---------------------------------------|-----------------------------------------------|------------------------------------|------------|-----------------------------------------------------|--------|-------|-----------------------------------|--------|-------|-----------------------------|--------|-------|-----------------------------------------------|---------------------------------------|------------------------------------------------------------|---------------------------------|
|    | NHTSA Recall Number | Canada DOT Recall Number | Prevost Recall # | Description                                                                         | Manufacturer | Date notification to purchasers began | Date notification to purchasers was completed | From...                            | Through... | USA                                                 | Canada | Total | USA                               | Canada | Total | USA                         | Canada | Total |                                               |                                       |                                                            |                                 |
| 17 | 13V-015             | 2013-014                 | SR13-03          | AFSS Linear Thermal Detector Replacement                                            | Prevost      | 2013-03-19 (epa us10)                 | 2013-06-11 (epa us07)                         | 2013-03-19                         | 2013-09-30 | 438                                                 | 69     | 507   | 298                               | 38     | 336   | 68                          | 55     | 66    | 0                                             | 0                                     | 0.5                                                        |                                 |
| 18 | 13V-021             | 2013-017                 | SR13-05          | NEW SIDE MARKERS WITH NON-REFLECT.                                                  | Prevost      | 2013-02-05                            | 2013-02-05                                    | 2013-02-05                         | 2013-09-30 | 45                                                  | 15     | 60    | 28                                | 10     | 38    | 62                          | 67     | 63    | 0                                             | 0                                     | 0.7                                                        |                                 |
| 19 | 13V-039             | 2013-059                 | SR13-07          | ECU SOFT UPDATE L-H IDLE PARAMET                                                    | Prevost      | 2013-05-02                            | 2013-05-02                                    | 2013-05-02                         | 2013-09-30 | 1062                                                | 431    | 1493  | 670                               | 289    | 959   | 63                          | 67     | 64    | 0                                             | 0                                     | 0.4                                                        |                                 |
| 20 | 13V-055             | 2013-139                 | SR13-08          | DRAGLINK TURNBUCKLE INSP. & REPL                                                    | Prevost      | 2013-05-02                            | 2013-05-02                                    | 2013-05-02                         | 2013-09-30 | 1442                                                | 472    | 1914  | 590                               | 257    | 847   | 41                          | 54     | 44    | 0                                             | 0                                     | 0.4                                                        |                                 |
| 21 | 13V-150             | n/a                      | SR13-26          | EMERGENCY EXIT SEQUENCE ON AWNING WINDOW DECALS                                     | Prevost      | 2013-08-01 (Interim Letter)           | 2013-08-30                                    | 2013-08-30                         | 2013-09-30 | 661                                                 | 58     | 719   | 19                                | 5      | 24    | 3                           | 9      |       | 0                                             | 0                                     | 0.1                                                        |                                 |
| 22 | 13V-278             | n/a                      | SR13-53          | Tail Lamp Photometrics                                                              | Prevost      | 2013-08-22                            | 2013-08-22                                    | 2013-08-22                         | 2013-09-30 | 28                                                  | 1      | 29    | 11                                | 1      | 12    | 39                          | 100    | 41    | 0                                             | 0                                     | 0.1                                                        |                                 |
| 23 | 13V-171             | n/a                      | SR13-80          | Mod. of Engine Speed Parameters for Limp Home Mode -Volvo D13 Engine ECU, SW Update | Volvo Bus    | 2013-07-02                            | 2013-07-02                                    | 2013-07-02                         | 2013-09-30 | 275                                                 | n/a    | 275   | 189                               | n/a    | 189   | 69                          | n/a    | 69    | 0                                             | 0                                     | 0.3                                                        |                                 |
| 24 | 13E-022             | n/a                      | Sr13-31          | MGM Type 24 J-series piston parking brake chamber                                   | Prevost      | 2013-08-21                            | 2013-08-21                                    | 2013-08-21                         | 2013-09-30 | 416                                                 |        | 416   | 277                               |        | 277   | 67                          |        | 67    | 0                                             | 0                                     | 0.1                                                        | Parts sold in after-market only |

**Comment:** Sr09-10 [nhtsa 9R-35], SR11-10 [11v-135] and sr11-52 [11v-364] removed as reported for more than 6 quarters;  
**Jan. 31 2014 :** NHTSA recall 13E-022 added, see item 24 above