

National Highway Traffic Safety Administration (NHTSA)
Vehicle Safety Recall Quarterly Progress Report for Fleetwood RV, Inc., a brand of Allied Recreation Group
Quarterly Report from October 1, 2013 through December 31, 2013
Report Date - January 30, 2014 / Report Author - Julie Jones (260) 724-5716

# of Quarters Reported	NHTSA Recall #	FRV Recall #	Date of 1st Mailing	Date of 2nd Mailing	Date of 3rd Mailing	Total # Vehicles Involved	Total # Inspected & Remedied	Total # Inspected & Not Requiring Remedy	Total # Exported	Total # Inspected / Defective / Owner Declined	Total # Unable to Notify	Description of Recall
6	12V-412	120813FRV	09/11/12	12/07/12	03/08/13	74	31	31	4	0	0	MY13 Excursion 33A Diesel Fuel Fill Hose - Inspect the diesel fuel fill hose for possible contact with a threaded fastener on the slide-out turn shaft.
5	12V-535	121025FRV	12/19/12	03/22/13	06/25/13	842	513	0	17*	0	11	MY10-13 Encel Storm-Terra (E mdi only) Entry Step Support - The entry step cage may become damaged by repeated use as a result of insufficient structural support and may separate from the sub-floor. (*Includes 1 exported to UK, 1 exported to Germany, 1 exported to Italy, 1 exported to Mongolia)
4	13V-007	130102FRV	01/31/13	04/26/13	07/26/13	14	6	0	0	0	0	MY12-13 Bdr CI 30T Federal Certification Tag Incorrect Rim and Tire Sizes and Pressures
3	13V-189	N/A	07/17/13	N/A	N/A	196	41	0	0	0	0	DOMETIC 13E-019 Power Awning Recall. Dometic implemented a design change on its power awnings. The design change altered the torque load on the awning motor such that the motor assembly screws absorb the rotational torque. Abnormal torque creates the potential to shear the motor assembly screws inside the awning roller tube, allowing the awning to unfurl unexpectedly. Dometic is handling all notifications.
3	13V-217	130517FRV	06/12/13	09/13/13	12/13/13	184	97	1	0	0	0	MY14 Am Rev, Bdr, Disc, Expd, Sthwnd. Solar panel attachment hdwe. on units built 3/20/13- 5/15/13.
3	13V-218	130417FRV	06/20/13	09/20/13	12/20/13	113	51	0	0	0	0	MY 13 Bdr CI and Terra Certification Label. Incorrect load index letter printed on labels. Correct load index letter is "G".
1	13V-580	131112FRV	01/17/14			774	2	0	0	0	0	MY14 All Products Indiana Mills Seat Belt Buckles, which are potentially noncompliant with the requirements of FMVSS No. 209.