



PREVOST

SAFETY RECALL

SR13-53

DATE : AUGUST 2013	SECTION : 06-ELECTRICAL
SUBJECT :	TAIL LAMP PHOTOMETRICS

APPLICATION

NOTICE TO SERVICE CENTERS

Verify vehicle eligibility by checking safety recall status with **SAP** or **Vehicle Warranty Information** tool found on Prevost-Systems tab of the Volvo Trucks Dealer Portal

Model	VIN	
X3-45 Coaches Model Year : 2013 - 2014	From 2PCG33491DC735388 up to 2PCG33491EC735487 incl.	
Le Mirage XL-II Entertainer Model Year : 2013	Single units: 2PCYS3497DC735404, 2PCY33491DC735461, 2PCYS3490DC735468, 2PCY33499DC735479	
This Safety Recall does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this recall will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.		

DESCRIPTION


On vehicles affected by this recall, the photometric intensity of the tail lamps exceeds the requirements outlined in Federal Motor Vehicle Safety Standard (FMVSS) No 108 'Lamps, reflective devices, and associated equipment'.

The tail lamp may appear to be brighter at certain points confusing following drivers about whether the vehicle is braking, increasing the risk of a crash.

Performing a multiplex software update in a Prevost Service Center will correct light intensity.

MATERIAL

No material is needed to perform this bulletin.



SPECIAL TOOLS

A laptop with VPG software installed and interface cable is required. Please contact your nearest Prevost Service Center for this update.

PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine and set battery master switch(es) to the OFF position prior to working on the vehicle.

1. Update the multiplex software with Vehicle Program Generator (VPG) to the following complist and revision.

X3-45 coaches:

Complist 06100058, rev P10 and up.

XLII Entertainers:

Complist 06100061, rev P12 and up.

WARRANTY


This modification is covered by Prevost's normal warranty. We will reimburse you the parts and half an hour (0.5h) of labor upon receipt of a completed A.F.A. form on which you must specify as per "Safety Recall 13-53". **You also have to fill the "Safety Recall Certification Sheet" provided with this bulletin and return it with your A.F.A. form to be reimbursed.**

OTHER

VBC Bulletin	n/a
Fail Code	06.27-1
Defect Code	4-49
System Condition	R
Causal Part	umisc

Access all our Service Bulletins on
<http://prevostparts.volvo.com/technicalpublications/en/pub.asp>
Or scan the QR-Code with your smart phone.



**PREVOST**

Safety Recall Certification Sheet (Ref: SR13-53)

VEHICLE SERIAL NUMBER:

2	P	C															
---	---	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

PERFORMED BY		OWNER/OPERATOR	
We hereby certify that Safety Recall Instructions with regard to Safety Recall SR13-53 have been performed.			
Name: _____		Name: _____	
Addr: _____		Addr: _____	
_____		_____	
_____		_____	
_____		_____	
Phone: _____		Phone: _____	
Fax: _____		Fax: _____	
Signature : _____		Signature : _____	
Date: _____		Date: _____	

If the information mentioned above is incorrect or you are not the owner of this vehicle anymore, please fill this section and return to sender.

NEW OWNER:

BUSINESS:

ADDRESS (including County):

TELEPHONE: _____

FAX: _____

Please return this completed document with your A.F.A. form