

September 12, 2014

Mr. Phil Hartnagel Senior Manager Product Investigation and Campaigns Chrysler Group LLC 800 Chrysler Drive CIMS 482-00-91 Auburn Hills, MI 48326-2757

Subject: Driver Door Wire Harness Insufficient Gauge

Dear Mr. Hartnagel:

This letter serves to acknowledge Chrysler Group LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: CHRYSLER/200/2015

Mfr's Report Date: August 5, 2014

NHTSA Campaign Number: 14V-480

Components: ELECTRICAL SYSTEM:WIRING

Potential Number of Units Affected: 8

Problem Description:

Chrysler Group LLC (Chrysler) is recalling certain model year 2015 Chrysler 200 vehicles manufactured May 19, 2014, to June 21, 2014. The affected vehicles may have been built with a driver side door wiring harness of an insufficient wire gauge, resulting in excessive heat which may melt the wiring insulation.

Consequence:

Excessive heat and melting wiring insulation may result in an electrical short, increasing the risk of a fire.

Remedy:

Chrysler will notify owners, and dealers will replace the door wiring harness, free of charge. The recall is expected to begin in September 2014. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is P43.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

1200 New Jersey Avenue SE Washington, DC 20590

> NVS-215SM 14V-480



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigations Enforcement

