



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 5, 2014

Jim Holliday
Technical Information & Warranty Mgr
Elgin Sweeper Company Inc.
1300 W. Bartlett Rd
Sycamore, IL 60178

NVS-215SM
14V-666

Subject: Hydraulic Oil Cooler Wiring Harness

Dear Jim Holliday:

This letter serves to acknowledge Elgin Sweeper Company Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

ELGIN/BROOM BADGER/2012-2014

Mfr's Report Date: October 21, 2014

NHTSA Campaign Number: 14V-666

Components:

ENGINE AND ENGINE COOLING:ENGINE:DIESEL

Potential Number of Units Affected: 92

Problem Description:

Elgin Sweeper Company Inc. (Elgin) is recalling certain model year 2012-2014 Broom Badger sweeper trucks manufactured March 1, 2013, to October 1, 2014. The affected vehicles are equipped with a modification hydraulic oil cooler fan wiring harness. The oil cooler fan may fail and cause overheating.

Consequence:

If the oil cooler fan fails and the hydraulic system overheats, a vehicle fire could result.

Remedy:

Elgin will notify owners, and dealers will install a modified wiring harness that separates ground wires from the fan and sending unit, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Elgin customer service at 1-847-741-5370. Elgin's number for this recall is SB-0148.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

You are required to provide an estimated date including month, day, and year, when you will send notifications to owners, dealers, and distributors as soon as it becomes available. Please be reminded that it is required that owners be notified of a safety defect in their vehicles within 60 days of a manufacturer's notification to NHTSA of a safety defect in those vehicles.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian". The signature is fluid and cursive, with a long horizontal stroke at the end.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement