

December 8, 2014

Mr. John Kobylarz Automotive Safety Office Jaguar Land Rover North America, LLC 555 MacArthur Boulevard Mahwah, NJ 07430

Subject: Wire Harness Configuration

Dear Mr. Kobylarz:

This letter serves to acknowledge Jaguar Land Rover North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: JAGUAR/F/2014 JAGUAR/F-TYPE/2015

Mfr's Report Date: November 5, 2014

NHTSA Campaign Number: 14V-714

Components: ELECTRICAL SYSTEM:WIRING

Potential Number of Units Affected: 7,079

Problem Description:

Jaguar Land Rover North America LLC (Jaguar) is recalling certain model year 2014-2015 F-Type vehicles manufactured August 31, 2012, to October 22, 2014. In the affected vehicles the seatbelt harness connector which connects the Seatbelt Tension Sensor (STS) to the Occupant Classification Sensor Control Module (OCSCM) may not have been correctly wired. The OCSCM senses whether there is an occupant in the front passenger seating position, and the STS senses whether tension on the seatbelt indicates a child restraint is being used in the front passenger seating position. Both sensors provide information to the restraint control module (RCM) which informs whether the front passenger airbag should be activated, depending on whether the sensors detect the seat is occupied and/or that it is occupied by an adult passenger.

Consequence:

Should the STS not have been wired correctly, the front passenger air bag may not be suppressed, and may remain activated, even when a child restraint is placed in the front passenger seat or a small statured adult occupies that seat. In the event of a crash necessitating deployment of the front passenger air bag, a child may be at an increased risk of injury.

Remedy:

Jaguar will notify owners, and dealers will correct the harness connector wire configuration, free of charge. The recall is expected to begin January 5, 2015. Owners may contact Jaguar customer service at 1-201-760-8534. Jaguar's number for this recall is J047.



1200 New Jersey Avenue SE Washington, DC 20590

> NVS-215SM 14V-714

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please provide a toll-free number at which your owners and customers can contact the company in the event they require additional information concerning this recall.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigations Enforcement

