



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 18, 2014

Sinan Senyurek
Tems Global Sanayi Ve Ticaret A.S.
Yol Gecen Mahallesi Turhan Cemal Beriker
Bulvari
NO: 561, 563 Seyhan Adana 01355

NVS-215KS
14V-768

Subject: Headlamps and Driving Lights may Fail

Dear Sinan Senyurek:

This letter serves to acknowledge Temsa Global Sanayi Ve Ticaret A.S.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

TEMSA/TS45/2014-2015

Mfr's Report Date: December 2, 2014

NHTSA Campaign Number: 14V-768

Components:

EXTERIOR LIGHTING:HEADLIGHTS

Potential Number of Units Affected: 38

Problem Description:

Tems Global Sanayi Ve Ticaret A.S.(Tems) is recalling certain model year 2014-2015 TS45 motorcoaches manufactured April 1, 2014, to November 30, 2014. Due to a headlamp control module malfunction, the headlamps and daytime running lamps may fail while driving.

Consequence:

If the headlamps and daytime running lamps fail while driving, there would be a loss of visibility, increasing the risk of a crash.

Remedy:

Tems will notify owners, and CH Bus Sales dealers will remove the affected headlamp control module and update the buses software, free of charge. The recall began on December 9, 2014. Owners may contact CH Bus Sales, representatives of Temsa, at 1-407-271-8935.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

Per the requirements of 573.6(c)(2)(iv), please provide the supplier name, contact information, address and country of origin (if known) for the headlamp control module.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian". The signature is fluid and cursive, with a large initial "J" and a long horizontal stroke at the end.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement