



April 17, 2014

Subject: Safety Recall (SC0379, Electronic Flasher)**Attention:**

Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue, S.E.
Washington, DC 20590

Submitted via Email

The following information is submitted in accordance with the requirements of 49 CFR Part 573.6 as it applies to a defect relating to motor vehicle safety.

573.6(c) (1)

Mack Trucks Inc. ("Mack Trucks")
7900 National Service Rd.
Greensboro, NC 27409

573.6(c) (2)

Certain vehicles manufactured from February 28, 2006 through November 8, 2013 with a Hamsar Electronic Flasher (Part Number 40-13247M0463)

Models affected:

CHU, CXU, and MRU: 2010 – 2014
CT and CV: 2007
GU: 2008-2014
LEU and TD: 2011-2014

The selection of vehicles was based on the component part number.

Component Manufacturer:

Hamsar Diversco Inc.
5320 Downey Street
Burlington, ON L7L 6M2

573.6(c) (3)

The total number of vehicles affected by the recall that were sold to customers in the United States is forty four thousand forty seven (44,047).

573.6(c) (4)

The percentage of the vehicles containing the defect is unknown.

573.6(c) (5)

The flasher may prematurely fail. If this occurs, the hazard warning lights may not function and therefore may not alert other drivers, which may increase the risk of personal injury or a vehicle crash.

Mack Trucks has not received reports of personal injury or vehicle crashes as a result of this condition.

573.6 (c) (6)

Chronology of principle events that were the basis for the determination:

- 7/12/13 NHTSA requests information on a Mack Trucks Field Service Bulletin
- 8/6/13 Requested information provided to NHTSA
- 10/9/13 Additional information collected and provided to Volvo Group North America Regulatory Affairs department for further evaluation
- 4/10/14 Product Safety Committee determines that a safety-related defect exists
- 4/17/14 Safety-related defect report submitted to NHTSA

Mack Trucks has identified nine hundred sixty (960) warranty claims that may be associated with the defect. There have been no reports of person injury or vehicle crashes.

573.6(c) (7)

Not applicable

573.6(c) (8)

Mack Trucks will initiate a voluntary owner notification, and recall all affected vehicles. The number, which has been assigned to this recall by Mack Trucks, is SC0379.


The recall repair will consist of replacing the electronic flasher.

Reimbursement for cost incurred by the owner for “prenotification remedies” will be addressed on a case-by-case basis according to the “General Plan for Reimbursement of Pre-notification Remedies” which was published October 28, 2013.

Owner letters are to be mailed within 60 days of this notice. An advance copy of the owner letter will be provided for NHTSA's review and approval prior to release.

If there are any questions regarding this information, please feel free to contact me.

Best Regards,

A handwritten signature in black ink, appearing to read "Tim LaFon", with a long horizontal line extending to the right.

Tim LaFon
Vice President, Regulatory Affairs
Volvo Group North America LLC
7900 National Service Rd.
Greensboro, NC 27409
timothy.lafon@volvo.com
(336) 393-2233