

Part 573 Safety Recall Report**14V-559****Manufacturer Name :** Lion Bus Inc.**Submission Date :** SEP 11,2014**NHTSA Recall No. :** 14V-559**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Lion Bus Inc.

Address : 921, chemin de la Riviere-du-Nord
Saint-Jerome, Quebec, Canada 00 J7Y 5G2

Company phone : 1-855-546-6706

Population :

Number of potentially involved : 0

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2014-2014 Lion 360

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : lack of glue on a ceiling joint can cause injury in case of an accident

Production Dates : AUG 09, 2014 - NOV 09, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : we have a vehicle that is in testing procedure and a joint split during the testing procedure

Description of the Safety Risk : in case of an accident the ceiling joint can split

Description of the Cause : lack of glue

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : we will have to supply a procedure by adding rivets to the 2 ceiling joints to add strenght

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : to follow

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported