

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

August 2014 Jayco dealer reported that two (2) units (TP0097 0098) arrived with roof ladder on the wrong side of the trailer. Production facility was contacted immediately to investigate. Production immediately inspected ALL units (not just TP trailers) on hand and found no units displaying the ladder on the wrong side of the unit. Further investigation found that two (2) units TP0095 0096 were noted during quality check to have ladder on the wrong side, and were repaired by production prior to shipping. The units repaired on site were the first in a production run of the TP model, subsequently Jayco decided a safety recall would be required to all TP model travel trailers that were produced during the same run (with the roof Ladder option) to ensure the location of the roof ladder, since none were still available for on site inspection.

Description of Remedy :

Description of Remedy Program : All affected units will be inspected for the correct placement (Off Door Side) of the roof ladder. If found on the wrong side (Door Side) of the trailer, a backer will be added to secure the ladder to the trailer

How Remedy Component Differs from Recalled Component : Correct location of the roof ladder . Correct being Off Door Side(Road Side) .. Incorrect being Door Side (Curb Side)

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Jayco will notify Dealers and Owners upon receiving recall Number and approval from NHTSA

Planned Dealer Notification Date : SEP 30, 2014 - SEP 30, 2014

Planned Owner Notification Date : SEP 30, 2014 - SEP 30, 2014

* NR - Not Reported